

## SIGNIFICANT ITEMS

Some of the potentially significant expenses over the short term are identified below. This page must not be considered as the complete report. Please read all other forms and appropriate text. Any items marked "0" under time frame should be treated as priority items.

Roofing	Flat roof is older and may need replacing within 3-5 yrs.
Exterior	Garage is in need of removal, rebuilding or major overhaul
Structure	
Electrical	
Heating	Furnace is older and may need replacing within the next 5 yrs.
Cooling/ Heat pump	
Insulation	
Plumbing	
Interior	

## OVERALL RATING

The following rating reflects both the original quality of construction and the current condition of the home, based on a comparison to similar homes.

<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
--------------------------	--------------------------	--------------------------	--------------------------	-------------------------------------	-------------------------------------	--------------------------	--------------------------	--------------------------

Below Average

Typical

Above Average

Overall rating would be a step higher if not for the garage.

Location References:

☒ Note: For the purpose of this report, the front of the house is considered to be facing:

N S E W

OR

☐ Note: For the purpose of this report, assume you are standing on the street facing the front door.

F is the front      LH is the left  
R is the rear      RH is the right

# HOME INSPECTION REPORT – ROOFING, FLASHINGS AND CHIMNEYS

THE HOME REFERENCE BOOK®

## DESCRIPTION

**1.0 Roofing Material:** ☒ 1.1 Asphalt ☐ 1.2 Wood ☐ 1.3 Slate ☐ 1.4 Concrete/Clay ☐ 1.5 Fiber Cement ☐ 1.6 Metal ☐ 1.7 Corrugated Plastic ☐ 1.8 Built-up ☒ 1.9 Roll Roofing ☒ 1.10 Modified Bitumen ☐ 1.11 Single-ply Plastic/Rubber ☐ 1.12 Polyurethane ☐ 1.13 Other

**3.0 Chimneys:** ☒ Brick ☐ Metal (Stucco cover) ☐ Partially Removed ☐ Abandoned ☐ Metal ☐ Metal (Wood cover) ☐ Stone ☐ Asbestos Cement ☐ Metal (Masonry cover) ☐ Mutual ☐ None

**4.0 Probability of Leakage:** ☐ High ☐ Medium ☒ Low

## LIMITATIONS

**Chimney/Flashing Inspection limited by:** \_\_\_\_\_

**Roof Inspection by:** ☐ Binoculars ☐ Ladder at edge ☒ Walking on ☐ \_\_\_\_\_

**Roof Inspection limited/prevented by:** ☐ Deck ☐ Gravel ☐ No access ☐ Snow/Ice ☐ Trees ☐ \_\_\_\_\_

☐ Another building ☐ Fragile ☐ Height ☐ Slope ☐ Solar panels ☐ Wet

☒ Asbestos may be present in many building products and materials. Environmental Consultants can assist if this is a concern.

☒ Moisture problems may result in visible or concealed mold growth. Environmental Consultants can assist if this is a concern.

## IMPROVEMENT RECOMMENDATIONS

☐ NO RECOMMENDATIONS AT PRESENT

TASK LOCATION TIME

TEXT REFERENCE	1.14.1/2	ROOFING – Sloped – blisters, branches touching roof, cracks, curled, damage, delaminated, flashings, ice dam (1.14.2), leaks, loose, manufacturing defects, missing, near end of life, old/worn out, loss of granules, patched, poor installation, rot, rust, too many layers, split, unsuitable materials, vulnerable areas				
	1.14.1/3	ROOFING – Flat – blisters, branches touching roof, buckling, cracks, curled, damage, delaminated, flashings, leaks, loose, loss of granules, manufacturing defects, near end of life, old/worn out, open seams, patched, ponding, poor installation, rot, rust, too many layers, split, unsuitable materials, vulnerable areas, wrinkling				
	2.0	FLASHINGS – replace when re-roofing				
		FLASHINGS – Valley 2.1, Hip and ridge 2.2, Sloped roof to flat roof 2.3, Roof to wall 2.4, Chimney 2.5, Parapet wall 2.6, Plumbing stack, Electrical mast, Exhaust flue 2.7, Skylight 2.8, Drip edge 2.9, Gravel stop 2.10, Roof vent 2.11				
		damage, deteriorated, incomplete, leaks, loose, missing, nail heads exposed, near end of life, old/worn out, open joints, overshoots gutter, pitch pan, patched, ponding, poor installation, rust, saddle, split, skylight curb, suspect, too close to siding, torn, valleys obstructed				
	3.0	CHIMNEY(S) – bracing, creosote build-up, debris, gap in liner, height suspect, leaning masonry/mortar deteriorated, rust, screen, stucco deteriorated, unlined flue				
		Cap – cracks, deteriorated, ineffective, missing	R		2	\$300-600

## COMMENTS

☐ See Supplementary Section ☐ Inappropriate Materials or Installation

Sloped roof is newer and in good condition.  
Flat roof is older (approx 15-16 yrs). Have inspected every two years. It may need replacing in 3-5 yrs: \$3000-6000

# HOME INSPECTION REPORT – EXTERIOR

THE HOME REFERENCE BOOK®

## DESCRIPTION

**1.0 Gutters & Downspouts:** ☐ Aluminum ☒ Galvanized Steel ☐ Integral/Built-in ☒ Discharge Below Grade  
☐ Copper ☐ Plastic ☐ Discharge Above Grade

**2.0 Lot Grading:** ☒ Away from House ☒ Flat ☐ Ravine ☐ Towards House

**3.0 Wall Surfaces:** ☒ 3.2 Brick ☐ 3.13 Fiber Cement ☐ 3.10 Metal ☐ 3.11 Vinyl  
☐ 3.12 Asphalt Shingle ☐ 3.14 Clay and Slate ☐ 3.9 Hardboard and Plywood ☐ 3.3 Stone ☐ 3.8 Wood  
☐ 3.4 Artificial Stone ☐ 3.5 Concrete Block ☐ 3.15 Insulbrick ☐ 3.6/3.7 Stucco/EIFS

**8.0 Retaining Walls:** ☐ Concrete ☒ Masonry ☐ Stone ☐ Wood ☐ Other

## LIMITATIONS

- ☐ Absence of historical clues due to new finishes/paint/trim ☐ No access/Car/Storage in garage  
☐ Carpeting/Snow over steps/decks/porches ☒ Restricted/No access under steps/Decks/Porches  
☒ Exterior inspection from ground level ☐ Storage against/inaccessible wall  
☐ Garage door opener not tested ☐ Vines, shrubs, trees, etc., against building restricted inspection  
☐ Grading not visible due to snow ☐
- ☒ Asbestos may be present in many building products and materials. Environmental Consultants can assist if this is a concern.  
☒ Moisture problems may result in visible or concealed mold growth. Environmental Consultants can assist if this is a concern.

## IMPROVEMENT RECOMMENDATIONS

☐ NO RECOMMENDATIONS AT PRESENT

TASK LOCATION TIME

TEXT REFERENCE	1.0	GUTTERS AND DOWNSPOUTS – clogged, damage, dented, discharge onto roof, discharge too close to home (6 ft.), end cap, holes, leaks, loose missing, not enough downspouts, old, paint, poor connections, rust, seams open, slope, split, worn out <i>→ should discharge above ground 6' from house</i>	R	W	1	\$250-500
	2.0	LOT GRADING – drain, erosion, low areas, risk of basement leakage, slope away from house, swale				
	2.1	Window well(s) – damage, drain poor, missing, rot, rust, too shallow, wood/soil contact				
	3.0	WALLS – cracks, efflorescence, foundation wall too short, kickout flashings, masonry/mortar deteriorated, parging deteriorated, planter/garden built up against wall, vines, weep holes below grade, wood/soil contact Siding/Soffit/Fascia – buckled, bulging, concealed damage?, cracks, damaged, delaminated, dented, leaks, loose, missing, paint/stain, poorly installed, split, rot, too close to grade, too close to roof, utility entrance, vent, worn out <i>to be installed @ back door.</i>	R	V	3	\$500-800 (includes chimney)
	4.0	DOORS/WINDOWS/TRIM – caulking deteriorated, damage, flashing defects, leaks, loose, missing, open joints, paint/stain, poorly installed, rot, rust, vermin damage, Door threshold/Window sill – damage, low, poor slope	I	V	M	
	5.1	STEPS – damage, inappropriate materials, paint/stain, rise/run problems, rot, settled, spalled, springy, trip hazard, wood/soil contact Landing – deteriorated, missing, slope, too small				
	5.2	RAILINGS – climbable, damage, missing, loose, openings too big, paint/stain, rot, rust, too short				
	5.3	COLUMNS – damage, leaning, rot, rust, settled, spalled, wood/soil contact				
	5.4/5	BEAMS/JOISTS/FLOORS – damage, end bearing, poor connection, rot, sag, wood/soil contact <i>2nd floor balcony does not appear to meet modern standards</i>				
	6.0	GARAGE/CARPORT – disrepair, door defects, door operator defects, leaning, low quality, rot, wood/soil contact – Due for demolition/repair: \$10,000-30,000 & rebuild Floor – cracks, poor drainage, settled, uneven				
	7.0	LANDSCAPING/WALKS/DRIVEWAY – branches touching home, old, poor slope for drainage, trip hazard				
	8.0	RETAINING WALL – bowing, cracks, leaning, movement, poor drainage?, rot	R	S	U	

## COMMENTS

☐ See Supplementary Section ☐ Inappropriate Materials or Installation ☒ See Windows and Doors in Interior Section

† These items may contribute to Basement/Crawl Space Leakage. Please see Interior Form.

# HOME INSPECTION REPORT – STRUCTURE

THE HOME REFERENCE BOOK®

## DESCRIPTION

- 2.0 Configuration: ☒ 2.1 Basement ☐ 2.2 Crawl space ☐ 2.3 Slab-on-grade
- 4.0 Foundations: ☐ 4.4 Piers ☐ 4.3 Piles ☒ 4.1 Poured Concrete/Masonry ☐ 4.2 Wood ☐ Not Visible
- 5.0 Floors: ☐ 5.6 Concrete ☐ 5.4.2 Engineered wood ☒ 5.4.1 Joists (Wood) ☐ 5.4.7 Steel ☐ 5.4.3 Trusses ☐ Not Visible
- 6.0 Exterior Walls: ☐ 6.1.6.3 Panelized ☐ 6.1.6.6 Straw Bale ☐ Not Visible  
☐ 6.1.5 Insulating Concrete Forms ☐ 6.1.6.2 Post and Beam ☐ 6.1.6.4 Structural Insulated Panel  
☐ 6.1.6.1 Log ☐ 6.1.6.5 Rammed Earth ☐ 6.1.2 Wood Frame  
☒ 6.1.1 Masonry ☐ 6.1.3 Steel Frame ☐ 6.1.4 Wood Frame – Brick/Stone Veneer
- 7.0 Roof/Ceiling Framing: ☐ 7.3 Steel Framing ☐ 7.1 Wood Rafters/Joists ☐ 7.2 Wood Trusses ☐ Not Visible

## LIMITATIONS

- Restricted/No access to: ☐ Attic ☐ Knee wall areas ☐ Slab-on-grade  
☐ Crawl space ☐ Roof space ☒ 20 % of interior foundation wall not visible
- ☒ Asbestos may be present in many building products and materials. Environmental Consultants can assist if this is a concern.  
☒ Crawl space/Roof space/Knee wall areas/Attic/Inspected from access hatch/Entered but access was limited  
☒ Moisture problems may result in visible or concealed mold growth. Environmental Consultants can assist if this is a concern.

## IMPROVEMENT RECOMMENDATIONS

☐ NO RECOMMENDATIONS AT PRESENT

TASK LOCATION TIME

	GENERAL – 1.0 Why buildings move/9.0 Things that cause structure problems				
3.0	FOOTINGS – missing, settlement, suspect	} Typical settling			
4.0	FOUNDATIONS – bowing, cracks, damage, lateral support poor, rot, settlement, spalling, too short				
5.0	FLOORS – inappropriate materials, poor installation				
5.1	Sills – below grade, crushed, damage, not well secured, rot, wood/soil contact				
5.2	Beams – crushed, damage, end bearing, lateral support, not well secured, rot, rust				
5.3	Columns – damage, footing missing?, not well secured, out of plumb, rot, rust, spalling				
5.4	Joists/Trusses – below grade, concentrated loads, cracks, damaged, end bearing, hanger defects, not well secured, poor connections, rot, rust, stiffeners/squash blocks?, weak at opening				
5.6	Concrete Floors – arch problems, broken, cracks, poor slope, settlement, uneven				
6.0	WALLS – inappropriate materials, poor installation				
6.1.1	Masonry – arch/header problems, bow, corbel excessive, cracks, lean, masonry/mortar deteriorated				
6.1.2	Wood Frame – buckled, damage, rot, weak at opening, wood/soil contact				
6.1.4	Wood Frame/Masonry Veneer – arch/header problems, bow, corbel excessive, cracks, lean, masonry/mortar deteriorated, rot, weep holes, wood/soil contact				
6.1.3	Steel Frame – improper holes, rust, weak at openings				
7.0	ROOFS – inappropriate materials, poor installation				
7.1/2	Wood Rafters/Trusses – bracing, cut, damage, connections, rot, sag, spreading, uplift				
7.3	Steel Frame – connections, holes, rust				
7.4-6	Collar Ties, Purlins, Knee Walls – bracing, buckled, damage, connections, location, rot, sag				
7.7	Sheathing – delaminating, edge support, mold, rot, sag				
8.0	CHIMNEYS – 3-sided, combustible clearance, corbel, cracks, fire blocking, leaning, pulling away from home, settlement, masonry/mortar deteriorated				

## COMMENTS

- ☐ See Supplementary Section ☐ Inappropriate Materials or Installation

– This house has a slight lean to the east – This is likely due to settling at the time the house was built

– The party wall is masonry (double brick) to the top of the roof.

## HOME INSPECTION REPORT – ELECTRICAL

THE HOME REFERENCE BOOK®

## DESCRIPTION

2.2 Service Entrance Conductors: ☐ Aluminum ☐ Copper ☐ Not Visible ☒ Overhead ☐ Underground

2.3 Service Size: \_\_\_\_\_ / \_\_\_\_\_ / 100 Amps (240Volts) 2.4 Main Disconnect/Service Box: ☒ Breakers Location West Basement  
☐ Fuses Rating \_\_\_\_\_ / \_\_\_\_\_ / 100 Amps (240Volts) ☐ Fuses

2.5 System Grounding: ☐ Aluminum ☒ Copper ☐ Ground Rods ☐ Not Visible ☐ Ufer ☒ Water Pipe ☐ \_\_\_\_\_

3.0 Service Panel: \_\_\_\_\_ / \_\_\_\_\_ / 100 Amps ☒ Breakers ☐ Fuses Sub-panel(s): ☐ Breakers ☐ Fuses Location \_\_\_\_\_

3.4 Ground Fault Circuit Interrupter: ☒ Bathrooms ☐ Kitchen ☒ Outside ☐ Whirlpool  
☐ Basement ☐ Garage ☐ None ☐ Panel ☐ \_\_\_\_\_ 3.5 Arc Fault Circuit Interrupter:  
☐ Panel ☒ None

4.0 Branch Circuit Wiring: ☐ Aluminum to Major Appliances ☐ Copper-clad Aluminum ☐ Metallic Sheathed  
☐ Aluminum ☒ Copper ☒ Knob-and-tube Copper ☒ Non-metallic Sheathed

5.1 Outlets: ☒ Grounded ☐ Ungrounded Number: ☐ Minimal ☒ Typical ☒ Upgraded

## LIMITATIONS

Power off: ☐ Throughout ☐ In some areas ☐ Restricted/No access to \_\_\_\_\_

☒ Concealed electrical components not inspected ☒ Main disconnect cover not removed  
☐ Fuse block(s) not pulled ☐ System ground not visible/not accessible

## IMPROVEMENT RECOMMENDATIONS

☐ NO RECOMMENDATIONS AT PRESENT

TASK LOCATION TIME

TEXT REFERENCE	RECOMMENDATION	TASK	LOCATION	TIME
2.0	SERVICE ENTRANCE – inappropriate materials/installation			
2.1/2	Conduit/Cable – clearance, damage, drip loop, loose, not well secured, poor seal/connection Mast – height, damage, rot, rust			
2.3	Service Size – depends on lifestyle, inadequate, marginal, suspect			
2.4	Service Box – breakers/fuses too small, damage, overheating, poor access/connection/location, rust, too small			
2.5	System Grounding – damage, ineffective, missing/not found, poor connection, suspect			
3.0	SERVICE PANEL – inappropriate materials/installation			
3.1	Panelboard – crowded, damage to breakers/fuses/panel/wire, double taps, loose, obsolete, openings, overheating, poor access/connections/location, rust, too small, Cover – damaged, missing	1	B	D
3.1	Sub-panel – ground & neutral bonded, undersized/unprotected feed wire			
3.2	Fuses/Breakers – damage, double-tap, link missing on 240 volt/multi-wire circuits, loose, wrong size			
3.4/5	Ground/Arc Fault Interrupters – mis-wired, not provided, test faulty			
4.0	BRANCH WIRING – inappropriate materials/installation			
4.1	Wires – abandoned, damage, exposed to damage, extension cord, exterior wire wrong type, not well secured, open splices, overheating, too close to ducts/pipes, undersized	1	B	O M
4.2	Knob-and-tube – brittle, damage, fused neutral, obsolete, poor connections, replace when remodeling – minimal (3% or less) Active wire discovered,			
4.3	Aluminum – anti-oxidant missing, connectors not rated for Alum, overheating but no terminations discovered.			
5.0	RECEPTACLES, LIGHTS, SWITCHES, JUNCTION BOXES – inappropriate materials/installation			
5.1	Receptacles – damage, inoperative, mis-wired, obsolete, poor location, reversed polarity, too few, ungrounded, not suitable for outdoors Cover – damaged, missing, not suitable for outdoors			
5.2	Lights – damaged, heat lamp fire hazard, inadequate for stairs, inoperative, missing, not suitable for damp area, poor location, pot lights in insulated ceiling			
5.3	Switches – damage, inadequate for stairs, inoperative, obsolete, poor location, Cover – damaged, missing			
5.4	Junction Boxes – crowded, loose, poor location, Cover – damaged, missing	1	B	O M
5.5	Appliances – no air conditioner disconnect, disposal wiring defect, Ceiling fan – loose, too low - Improperly abandoned wire @ 2nd fl. balcony.			

## COMMENTS

- ☒ All recommendations are safety issues – Treat them as high priority  
☐ See Supplementary Section ☐ Inappropriate Materials or Installation



## HOME INSPECTION REPORT – HEATING

THE HOME REFERENCE BOOK®

<b>DESCRIPTION</b>	
2.0/1 Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Oil <input type="checkbox"/> Electricity <input type="checkbox"/> Wood	
Type: <input checked="" type="checkbox"/> 5.0 Furnace <input type="checkbox"/> 6.0 Hot Water Boiler <input type="checkbox"/> 7.0 Steam Boiler <input type="checkbox"/> 8.0 Electric <input type="checkbox"/> Stove/Space Heater <input type="checkbox"/> Combination System	
Distribution: <input checked="" type="checkbox"/> Ducts <input type="checkbox"/> Radiators/Convectors/Baseboards <input type="checkbox"/> Radiant <input type="checkbox"/> None	
Efficiency: <input checked="" type="checkbox"/> Conventional <input type="checkbox"/> Mid <input type="checkbox"/> High	Rated Input/Output: _____ / _____ / 105 MBTU/hr.
Approximate age: _____ / _____ 20 years	Life Expectancy: _____ 20-25 years
Chimney: <input checked="" type="checkbox"/> Masonry – Clay Lined, Metal Lined, Unlined <input type="checkbox"/> Metal <input type="checkbox"/> None	Fuel shut-off valve at: <u>gas meter</u>

<b>LIMITATIONS</b>		
<input type="checkbox"/> 16.3 A/C or heat pump operating <input checked="" type="checkbox"/> Chimney clean-out not opened <input type="checkbox"/> Circulating pump not tested <input checked="" type="checkbox"/> Heat exchanger not visible/inaccessible <input checked="" type="checkbox"/> Heat loss calculations not done <input checked="" type="checkbox"/> Asbestos may be present in many building products and materials. Environmental Consultants can assist if this is a concern. <input checked="" type="checkbox"/> Buried tanks are not included in the inspection. Environmental Consultants can assist if this is a concern.	<b>Data plate:</b> <input type="checkbox"/> Incomplete <input type="checkbox"/> Missing <input type="checkbox"/> Not legible	<input type="checkbox"/> Oil tank not visible <input checked="" type="checkbox"/> Radiator/Zone valves not tested <input checked="" type="checkbox"/> Safety devices not tested <input type="checkbox"/> 16.2 Summer test procedure <input type="checkbox"/> 16.1 System shut off/Inoperative

IMPROVEMENT RECOMMENDATIONS		<input type="checkbox"/> NO RECOMMENDATIONS AT PRESENT	TASK	LOCATION	TIME
TEXT REFERENCE	2.0	FUEL/VENTING – inappropriate materials, poor installation			
	2.2	Gas piping/tank – leak, no drip leg, poor support, <u>Propane tank</u> – near ignition source, under roof			
	2.2	Gas burner – dirty, flashback, misaligned, rusted			
	2.3	Oil tank/piping – damage, leak, poor location, rust, support suspect, wrong type			
	2.3	Oil burner – oil leak, poor adjustment, primary control defect, refractory deteriorated			
	2.4	Combustion/Draft air – inadequate, suspect			
	2.5	Venting/Chimney – <u>Vent connector</u> – combustible clearance, leak, length, material, poor connection to chimney, rust, size, slope, rust, <u>Barometric damper</u> – adjustment/rust, <u>Chimney</u> – cap missing, combustible clearance, liner needed, poor repair, rust, shared flue, support, <u>Sidewall vent</u> – damage, poor arrangement, poor location			
	3.0	THERMOSTAT – anticipator defect, damage, inoperative, poor location			
	5.0	FURNACE – blower defect, condensate leak, inoperative, electric element defect, heat exchanger defect <u>old</u> worn out, past normal life expectancy, rust, service, short cycling	R	B	4-5 \$3500-7000
	5.7	Filter – dirty, missing, <u>Humidifier</u> – inoperative, leak, missing damper			
5.10	Ducts/Registers/Grilles – balancing, different metals touching, ducts dirty, in concrete floor, missing, no airflow, poor connection, poor location, too few				
	Combination System – near end of life, no tempering valve, undersized?				
6.0/7.0	BOILER – Hot water/Steam – heat exchanger defect, inoperative, near end of life, old/worn out, rust, service, short cycling, water leak, <u>Pump</u> – inoperative, leak, noisy				
	<u>Expansion tank</u> – leak, rust, waterlogged?				
6.5	Controls – <u>Pressure reducing valve</u> – defective, leak, system not filled				
	<u>Backflow preventer</u> – missing, leak, <u>Low water cut out</u> – inoperative, leak				
	<u>Pressure relief valve</u> – capped, leak, poor discharge point				
6.7	Piping/Radiators – leak, missing, no heat, rust, <u>Radiant</u> – leak, no heat, <u>Valves</u> – inoperative, leak				
8.0	ELECTRIC HEAT – combustible clearance, damage, electrical defect, inoperative, obstructed				
	<u>Radiant</u> – cool spots, no heat				

<b>COMMENTS</b>	
<input type="checkbox"/> See Supplementary Section <input type="checkbox"/> Inappropriate Materials or Installation	
Supply Temp: _____ / _____ / _____	Return Temp: _____ / _____ / _____ ΔT: _____ / _____ / _____

# HOME INSPECTION REPORT – COOLING/HEAT PUMP

THE HOME REFERENCE BOOK®

## DESCRIPTION

Air Conditioning/Heat Pump: ☒ 1.1 Air Source ☐ 1.2/2.2 Water Source ☐ 2.2 Ground Source ☐ 1.3.2 Independent-ducted ☐ 1.3.3 Independent-ductless ☒ 1.3.1 Central ☐ 2.3 Bivalent ☐ 3.0 Evaporative Cooler

1.4 Cooling Capacity: \_\_\_\_\_ / \_\_\_\_\_ / 18 MBTU/hr. 1.5 Compressor Age (Approximate): \_\_\_\_\_ / \_\_\_\_\_ / 10 years

1.5 Life Expectancy: \_\_\_\_\_ / 15 years

## LIMITATIONS

Data plate: ☐ Incomplete ☐ Not found ☐ Outdoor coil covered ☐ System shut off/Inoperative  
☐ Missing ☐ Not legible ☐ Restricted access ☒ Heating system on  
 Outdoor temperature prevented testing in: ☐ Cooling mode ☒ Heat gain and heat loss calculations not done ☐ House fan not tested  
☐ Heating mode ☒ Window A/C excluded  
☒ Asbestos may be present in many building products and materials. Environmental Consultants can assist if this is a concern.  
☒ Moisture problems may result in visible or concealed mold growth. Environmental Consultants can assist if this is a concern.

## IMPROVEMENT RECOMMENDATIONS

☐ NO RECOMMENDATIONS AT PRESENT

TASK LOCATION TIME

TEXT REFERENCE	1.0	AIR CONDITIONING – old/worn out, oversized?, past normal life expectancy, undersized?			
	1.1.2	Compressor – electric disconnect missing, inoperative, not level, old/worn out, past normal life expectancy			
	1.1.3	Indoor/Outdoor Coil – airflow obstructed, appliance exhaust too close, damage, noisy, poor location, rust, temperature drop too big/small			
	1.1.4	Indoor/Outdoor Fan – damage, noisy, weak airflow, Filter – dirty, missing			
	1.1.5	Refrigerant Lines – corrosion, damage, leak, <u>Insulation</u> damage, missing	1	EXT	0 M
	1.1.6	Condensate System – Pipe – clogged, leak, missing, poor discharge location Pump – inoperative, noisy, Tray – leak, overflow			
	1.1.7	Ducts/Registers/Grilles – balancing, ducts dirty, in concrete floor, missing, no airflow, poor connection, poor location, too few			
	1.1.7	Attic Ducts – damage, leak, poor connection, <u>Insulation</u> – damage/missing Vapor barrier – damage, missing, poor location			
	1.1.8	Attic Drip Pan – clogged, drain defect, missing, leak, poor discharge location, poorly arranged, rust Secondary drain – defect, missing rust			
	1.1.9	Thermostat – anticipator defect, damage, inoperative, poor location, wrong type			
	2.0	HEAT PUMP – old/worn out, oversized for cooling?, past normal life expectancy			
	3.0	EVAPORATIVE COOLER – clogged, connected to heating ducts, dirty, inoperative, leak, near end of life, rust			

## COMMENTS

☐ See Supplementary Section ☐ Inappropriate Materials or Installation

Supply Temp: \_\_\_\_\_ / \_\_\_\_\_ / \_\_\_\_\_ Return Temp: \_\_\_\_\_ / \_\_\_\_\_ / \_\_\_\_\_ ΔT: \_\_\_\_\_ / \_\_\_\_\_ / \_\_\_\_\_

# HOME INSPECTION REPORT – INSULATION

THE HOME REFERENCE BOOK®

## DESCRIPTION

2.0 Material: ☒ Fiberglass ☐ Cellulose ☐ Mineral Wool ☐ Plastic Board ☐ Spray Foam ☐ UFFI ☐ Vermiculite ☐ Other

3.0 Location/4.0 Amount: ☒ Attic R 25  
☐ Basement R \_\_\_\_\_  
☐ Crawlspace R \_\_\_\_\_  
☐ Floor above Unheated Space R \_\_\_\_\_  
☐ Roof Space R \_\_\_\_\_  
☐ Wall R \_\_\_\_\_

5.0 Air/Vapor Barrier: ☐ Plastic ☒ Not Visible  
☒ Kraft Paper ☐ None Found

6.1 Roof Vent Type: ☒ Gable ☐ Power Vent  
☒ Roof ☐ Soffit ☐ None Found  
☐ Ridge ☐ Fascia

6.2 Crawlspace Vent Type: ☐ Into Basement ☐ None Found ☐ Wall

7.0 Heat Recovery Ventilator: ☐ Present

## LIMITATIONS

- Access not gained to: ☐ Attic ☐ Crawl space ☐ Floor space ☐ Knee wall areas ☐ Roof space ☐ Wall space
- ☒ Attic/Crawl space viewed from access hatch/Entered but access was limited
- ☒ Asbestos may be present in many building products and materials. Environmental Consultants can assist if this is a concern.
- ☒ Continuity of air/vapor barrier not verified
- ☐ Crawl space/Roof space/Knee wall areas/Attic/Inspected from access hatch/Entered but access was limited
- ☒ Moisture problems may result in visible or concealed mold growth. Environmental Consultants can assist if this is a concern.
- ☐ Power ventilator not tested ☐ Walls spot checked only

## IMPROVEMENT RECOMMENDATIONS

☐ NO RECOMMENDATIONS AT PRESENT

TASK LOCATION TIME

2.4	EXPOSED PLASTIC INSULATION – fire hazard				
3.1	ATTIC – amount, compressed, duct un-insulated, exhaust vents into attic, hatch weatherstrip, knee wall defect, missing, mold, pot light overheat?, skylight well defect, uneven, wet	I	A	D	\$300-600
	5.0 Air/vapor barrier – incomplete, missing, wrong place				
	Attic access hatch – air leakage, insulation, weatherstripping				
	6.0 Ventilation – damaged vents, not enough, obstructed, poor location				
3.2	Flat/Cathedral – amount, compressed, evidence of condensation, mold, pot light overheat?, uneven, wet, 5.0 Air/vapor barrier – incomplete, missing, wrong place, 6.0 Ventilation – suspect				
3.3	Walls – amount, voids, 5.0 Air/vapor barrier – incomplete, missing, wrong place				
3.4	Basement/Crawlspace – amount, none, Moisture barrier – ineffective, missing				
	Rim joist – amount, none, uneven, 5.0 Air/vapor barrier – incomplete, missing, wrong place				
	6.0 Ventilation – damaged vents, not enough, obstructed, poor location				
3.5	Floors above Unheated Areas – amount, duct/pipes un-insulated, uneven, voids, wet				
	5.0 Air/vapor barrier – incomplete, missing, wrong place				
7.0	HEAT RECOVERY VENTILATOR – blower noisy, condensate defect, inoperative, not balanced, poor inlet/exhaust termination, Filter – dirty, missing, Heat exchanger – damage, dirty, rust				

## COMMENTS

- ☒ See Comments on Page 3 of text re: Caulking and Weather-stripping. Please read Section 1.0 – Current Standards.
- ☐ See Supplementary Section ☐ Inappropriate Materials or Installation



# HOME INSPECTION REPORT – PLUMBING

THE HOME REFERENCE BOOK®

## DESCRIPTION

1.1/2 Service Piping into Home: ☐ Copper ☒ Galvanized Steel ☐ Lead ☐ Plastic (PE/PVC/PB/PEX) ☐ Not Visible

1.3 Main Water Shut-off Valve at: NE Basement

1.4 Supply Pipe in Home: ☒ Copper ☐ Galvanized Steel ☐ Plastic (CPVC/PEX/PB) ☒ Not Visible

1.6 Water Heater Type: ☒ Conventional ☐ Tankless ☐ Indirect ☐ Induced Draft 1.6 Fuel: ☐ Electricity ☒ Gas ☐ Oil

1.6 Water Heater Capacity: 50 Gallons 1.6 Water Heater Age: 20 Years 1.6 Water Heater Life Expectancy: 15 Years

2.3 Waste Piping: ☒ Cast Iron ☐ Copper ☐ Galvanized Steel ☒ Plastic (ABS/PVC) ☒ Not Visible

## LIMITATIONS

Fixtures not tested/Not in service: ☐ Basin ☐ Bidet ☐ Toilet ☐ Shower ☐ Hot tub ☐ Whirlpool bath  
☐ Bathtub ☐ Laundry tub ☐ Sauna ☐ Sink ☐ Water heater

☒ Asbestos may be present in many building products and materials. Environmental Consultants can assist if this is a concern.

☒ Concealed plumbing not inspected ☐ Gas/Water shut off/winterized

☒ Isolating/Relief valves & main shut-off valve not tested ☐ Laundry tub ☐ Main valve not located

☒ Moisture problems may result in visible or concealed mold growth. Environmental Consultants can assist if this is a concern.

☐ Restricted/No access to:

☒ Tub/Sink overflows not tested ☐ Water treatment equipment not inspected ☐ Well/Septic system not inspected

## IMPROVEMENT RECOMMENDATIONS

☐ NO RECOMMENDATIONS AT PRESENT

TASK LOCATION TIME

TEXT REFERENCE	1.0	SUPPLY – inappropriate materials, poor installation			
	1.1	Public Service Piping – lead, leak, low pressure/flow, pressure regulator needed, undersized			
	1.2	Private Supply – leak, low pressure/flow, Pump – inoperative, leak, noisy, short cycles			
		Tank – leak, rust			
	1.4	Piping in House – cross connections, damage, exposed to damage, low pressure/flow, leak, noise, polybutylene (PB) issues, rust, support, water hammer			
	1.3/5	Valves – handle damage, inaccessible, inoperative, leak, missing, rust			
	1.6	WATER HEATER – damage, inoperative, leak, past normal life expectancy, poor location, too small?	R B O (Rental).		
		Relief Valve and Tube – capped, missing, poor termination, size reduction			
		Combustion/Draft Air – inadequate, suspect, Vent – connections, length, material, slope			
	2.0	WASTE – inappropriate materials, poor installation			
	2.3	Piping – connections, clog, cracks, damage, holes, lead near end of life, leak, rust, slope, support			
	2.4/5	Traps/Floor drain – clog, cover defect, dry, missing, leak, poor configuration, primer defect, S-trap, wrong type			
	2.6	Venting – air admittance valve, automatic air vent, gurgling, incomplete, ineffective, missing, - Remove chicken wire on stack (roof).			
	2.7/8	Termination – frost, poor location, too short, too tall			
		Sewage/Sump Pump – clog, discharge defect, inoperative, leak, poor arrangement/installation			
		Lid – damage, missing			
	3.0	FIXTURES – low quality, poor condition			
	3.1-3	Sink/Basin – air gap missing, chipped, crack, cross connection, drain slow, leak, poorly secured, rust			
	3.4	Faucet – damage, drip, handle damage, inoperative leak, loose, old, reversed hot/cold, stiff			
	3.5	Outdoor Faucet – back flow preventer, damage, drip, handle damage, inoperative leak, loose, risk of freezing, slope, stiff			
	3.6	Toilet – crack, floor damage, inoperative, leak, loose, old, running continuously, seat defect, slow flush			
	3.7	Bathtub – chip, crack, damage, drain slow, leak, old, stain			
	3.8/9	Bathtub/Shower Enclosure – caulk, door defect, grout, leak, old, risk of concealed damage, rust			
		Tile – damaged, loose, missing, Diverter – damaged, inoperative, missing			
	3.10	Whirlpool Tub – GFCI missing, leak, Pump – inoperative/no access/noisy			
	3.12/13	Exhaust Fan – inoperative, missing, noisy, poor termination			

## COMMENTS

☐ See Supplementary Section ☐ Inappropriate Materials or Installation

# HOME INSPECTION REPORT – INTERIOR

THE HOME REFERENCE BOOK®

<b>DESCRIPTION</b>			
1.0 Floors: <input checked="" type="checkbox"/> Carpet <input type="checkbox"/> Ceramic tile <input type="checkbox"/> Concrete <input type="checkbox"/> Laminate <input checked="" type="checkbox"/> Resilient <input type="checkbox"/> Stone <input checked="" type="checkbox"/> Wood/Engineered wood			
2.0 Walls: <input type="checkbox"/> Concrete <input type="checkbox"/> Masonry <input type="checkbox"/> Ceramic tile <input checked="" type="checkbox"/> Drywall/Plaster <input type="checkbox"/> Wood		3.0 Ceilings: <input type="checkbox"/> Acoustic tile <input type="checkbox"/> Metal <input type="checkbox"/> Textured <input checked="" type="checkbox"/> Drywall/Plaster <input type="checkbox"/> Suspended tile	
6.0 Window Type: <input type="checkbox"/> Awning <input checked="" type="checkbox"/> Casement <input checked="" type="checkbox"/> Fixed <input type="checkbox"/> Hopper <input type="checkbox"/> Jalousie <input checked="" type="checkbox"/> Single/Double Hung <input checked="" type="checkbox"/> Skylight <input type="checkbox"/> Slider			
7.0 Exterior Door Type: <input type="checkbox"/> French <input type="checkbox"/> Sliding <input checked="" type="checkbox"/> Hinged <input type="checkbox"/> Storm		7.0 Exterior Door Material: <input type="checkbox"/> Fiberglass <input checked="" type="checkbox"/> Metal-clad <input checked="" type="checkbox"/> Wood <input type="checkbox"/> Metal <input type="checkbox"/> Vinyl-clad	
9.0 Fireplace/Stove Type: <input checked="" type="checkbox"/> Factory-built (zero-clearance) Fireplace <input type="checkbox"/> Fireplace Insert <input type="checkbox"/> Masonry Fireplace <input type="checkbox"/> Gas Logs <input type="checkbox"/> Stove		9.0 Fireplace/Stove Fuel: <input type="checkbox"/> Coal <input type="checkbox"/> Pellet <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Wood	
10.0 Basement/Crawlspace Leakage: <input type="checkbox"/> Cannot predict frequency or severity. Read Section 10.			

<b>LIMITATIONS</b>	
<input type="checkbox"/> Absence of historical clues due to new finishes/Paint <input checked="" type="checkbox"/> Asbestos may be present in many building products and materials. Environmental Consultants can assist if this is a concern. <input checked="" type="checkbox"/> CO Detectors, security systems, intercoms, central vacuum, chimney flues and elevators were not inspected <input checked="" type="checkbox"/> Drainage tile not visible <input type="checkbox"/> Fireplace in use <input checked="" type="checkbox"/> 20 % of foundation wall not visible <input checked="" type="checkbox"/> No comment made on cosmetic finishes <input checked="" type="checkbox"/> Quality of chimney draw cannot be determined <input type="checkbox"/> Restricted/No access to: _____ <input type="checkbox"/> Storage/Furnishings in some areas limited inspection <input checked="" type="checkbox"/> Moisture problems may result in visible or concealed mold growth. Environmental Consultants can assist if this is a concern.	

IMPROVEMENT RECOMMENDATIONS		<input type="checkbox"/> NO RECOMMENDATIONS AT PRESENT	TASK	LOCATION	TIME
TEXT REFERENCE	1.0 FLOORS – broken, buckled, cracks, damage, grout defect, loose, mold, old/worn out, slope, stain, torn, trip hazard, <u>typical minor flaws</u> , water damage				
	2.0 WALLS – bulge, cracks, damage, loose, nail pop, patch, rot, stain, <u>typical minor flaws</u> , water damage				
	3.0 CEILINGS – bulge, cracks, damage, loose, nail pop, patch, rot, stain, truss uplift, <u>typical minor flaws</u> , water damage				
	4/5.0 TRIM/CABINETS/COUNTERS – burns, cracks, damage, missing, loose, rot, water damage Cabinets – door defect, drawer operation, hardware defect, not well secured, old				
	6.0 WINDOWS – low quality, old/worn out, Windows/Skylights – damage, drainage, frame defect, gasket defect, hardware defect, inoperable, leak, <u>lost seal</u> , old, possible concealed damage, rot, sash defect, stiff, sash cord defect, sill, weather tightness, Glass – broken, crack, loose, putty, safety glass, Screen – missing, torn, worn out			R 2SW	D
	7.0 DOORS – damage, dent, drainage, frame defect, hardware defect, inoperable, leak, lost seal, rot, stiff, sill, threshold, weather tightness, Glass – broken, crack, loose, putty, safety glass, Screen – missing, torn, worn out, Garage – fire rated, gas-tight, man-door closer, Vehicle Door – auto-reverse, operability				
	8.0 STAIRS – Riser, Stringer, Tread – damage, headroom, loose, rot, support, uneven, width Railing – climbable, height, <u>missing</u> , loose, openings too big, rot, strength			P T	O
	9.0 FIREPLACE/STOVE – inspect/clean (as needed) before using and annually Fireplace/Stove – combustible clearance, draft suspect, flue pipe defect, settlement Chimney – connection to stove/insert, dirty, flue crack, gap, shared?, settlement, suspect Damper – damage, inoperative, missing, not well secured, rust, Firebrick – deteriorated, loose, missing, Hearth – crack, damage, missing, too small, Metal Firebox – buckled, damage, rust Gas fireplace – inoperative, inappropriate location, glass doors				
	10.0 BASEMENT/CRAWLSPACE LEAK – Cannot predict frequency/severity. <i>Read Section 10.</i> Evidence of moisture: dehumidifier, efflorescence, loose tiles, mold, odor, patch, peeling paint, rot, rust, stain, sump pump, water damage, wet, Possible Causes: 1. gutters/downspouts, 2. poor grading, 3. wall cracks, 4. high water table – <i>Address these in order. Read Section 10.</i>				
	11.0 SMOKE/CARBON MONOXIDE (CO) DETECTORS – missing, inoperative?, obsolete?				

<b>COMMENTS</b>	
<input type="checkbox"/> See Supplementary Section <input type="checkbox"/> Inappropriate Materials or Installation	

<b>TASK</b>	<b>CL</b> Clean <b>CO</b> Correct <b>D</b> Demolish	<b>FE</b> Further Evaluation <b>I</b> Improve <b>M</b> Monitor	<b>P</b> Provide <b>R</b> Repair or Replace
<b>LOCATION</b>	<b>1</b> First Floor <b>2</b> Second Floor <b>3</b> Third Floor <b>A</b> Attic <b>B</b> Basement <b>Bath</b> Bathroom <b>Bay</b> Bay <b>BAL</b> Balcony <b>BED</b> Bedroom <b>C</b> Central <b>CRA</b> Crawlspace <b>DE</b> Deck	<b>DO</b> Dormer <b>DR</b> Dining Room <b>E</b> East <b>ENS</b> Ensuite <b>EX</b> Exterior <b>F</b> Front of house <b>FAM</b> Family Room <b>G</b> Garage <b>H</b> Hall <b>LH</b> Left side of house <b>K</b> Kitchen <b>LA</b> Laundry Area	<b>LR</b> Living Room <b>M</b> Master <b>N</b> North <b>O</b> Office or Study <b>P</b> Porch <b>R</b> Rear of house <b>RH</b> Right side of house <b>S</b> South <b>T</b> Throughout <b>V</b> Various <b>W</b> West <b>WAS</b> Washroom
Note: the direction the house is assumed to face is noted on the Bottom Line page.			
<b>TIME</b>	<b>0</b> Immediate <b>1</b> Within one year <b>2</b> Within two years <b>"X"</b> Within "X" years	<b>D</b> Discretionary item (Improvements can be made, but are not critical) <b>M</b> Regular maintenance or ongoing	<b>U</b> Unpredictable (This component could last a few months or several years) <b>?</b> If necessary
<b>COST</b>	<b>B</b> Buyer is to perform the work <b>D</b> Dependent (Cost will depend on extent of work and approach taken. In some cases, the best approach cannot be determined during a one-time visual inspection.)	<b>M</b> Minor cost or regular maintenance item <b>MAJ</b> Major <b>L</b> Consult the Life Cycles and Costs section of the book <b>S</b> Seller or builder is to perform the work <b>&lt;</b> Less than	<b>&gt;</b> More than <b>=</b> Approximately
Note: Any figures given are very rough ballpark numbers. Several quotations from contractors should be obtained. Do not rely on any figures presented here to make a decision about owning a property. Our experience has shown that quotes often vary by 300%.			