

Visual Pre-Inspection Agreement

Name: UPNIO	HADREIN WIN	CHOISON				
Current Address	235 SYMING	ON AVE-	_City/ Province	e/ Postal	, by , o.	MBPIUM
Phone # 4 - 560	-6424	E-Mail:	indieno)	avidAn	noens Viki	Auson.com
Regarding: (Property	to be Inspected)	DATE Ap	r. 4/	16	Time:	:10 gm
Address: 235	Symington	Ave.	Unit #	City:	Toro	into
Inspections ("Inspect	or"):					anchisee of Lighthouse
For a Fee of \$	the Customer agrees the inspector. The Inspector	to have Inspector of will provide the Cu	conduct a home in ustomer with a 38	nspection for t	the purpose of o	utlining any visual major for the exclusive use and
possession of the Custom	er. The written report will in	clude comments ba	sed on observation	ons of the visi	ble and accessil	ble parts of components only
limited visual home insper	to assist in evaluation of the ction of the exposed elemen	e overall condition ts of maior compor	of the home / buil ents of the home	and substant	the advisability of ial deficiencies r	of the purchase. This will be a
because of the limited nat	ure of such an inspection. I	he inspection is b	ased on observa	ation of the v	isible and appa	arent condition of the
building and its compor	ents, in readily accessible	areas only, on th	e date of the ins	pection, at th	ne time of the in	nspection.
The inspector does not pe	rform invasive procedures n	or will equipment, i	tems and systems	s be dismantle	ed. The inspecto	or only uses normal operating
be discussed, but they are	not a part of the inspection	and report See F	clusions and Li	or functions. N	raintenance, cos	smetics and other things may
	part at allo mepoduon		olesions and En	interioris list	ou bolow	

Concerns: The Inspector extends to its Customers the invitation to contact the inspector at any time should any concern or question arise in connection with the inspected property. The Inspector is committed to resolving customer concerns in a timely manner. The Client acknowledges that the above noted Inspector is an independently owned and operated Franchisee of Lighthouse Inspections Canada Limited. Inspector and its employees are limited in liability to the fee paid for the inspection services and Report in the event that the Client or third party claims that Inspector is in any way liable for negligently performing the inspection. Client hereby agrees to indemnify, defend and hold harmless Inspector and Lighthouse Inspections Canada Limited if any third party brings a claim relating to this Inspection Report.

Notice: The Client acknowledges and agrees that any claim(s) or complaint(s) arising out of or related to this Visual Inspection shall be reported to Inspector, in writing within ten (10) days of its detection in order to allow the Inspector the opportunity to re-inspect that portion of the home in dispute prior to any renovations or repairs relating to the concern in the Report.. Any claims must be presented within one (1) year from the date of the inspection; Inspector will have no liability for claims presented after this time.

Exclusions and Limitations

The Inspector is limited to a visual inspection of the building only, any areas that are blocked by finishing materials, storage, furniture, or environmental factors are therefore eliminated from the scope of this inspection. The role of the home inspector is as an educator, to provide you with an understanding of the home and it's components. Annual maintenance costs run approximately 3 to 5% of the purchase price.

The Inspector does not assess:

- · Aesthetic or cosmetic concerns (i.e., finishes, odours, cleanliness); Design or adequacy of rooms or the home in general or compliance to UL or CSA standards
- · Quality of workmanship or material that does not affect the structural integrity or safety of the home.
- · Building codes as these are revised on an ongoing basis and are not standard across municipalities. Local building officials assess code compliance
- Life spans and age of elements and/or components. Indications are estimates only, the inspector cannot guarantee that such items will last for their expected
 life span, including but not limited to life expectancy and failure of components
- Attics will rarely be entered, in most cases, the inspector will perform a general inspection from the access hatch, where accessible
- Ancillary elements including, but not limited to, barbecues, site lighting, solar heating panels, satellite dishes, irrigation systems, security systems, sprinkler systems, central vacuum systems
- Inspect roofs that are not visible from the ground with binoculars or not accessible from a 13-foot ladder. Inspectors do not walk roofs; to do so may cause
 leaks or other damage at the time or within months of the inspection and could affect the roof warranty.

Please see Page 2 of this Pre-Inspection Agreement. _____CUSTOMER INITIALS

© Lighthouse Inspections

EACH OFFICE IS INDEPENDENTLY OWNED AND OPERATED

Page 1 of 2

Visual Pre-Inspection Agreement - Page 2

The Inspector cannot:

- Move personal belongings, storage or furniture, finishing, carpeting snow, ice, earth, etc., to gain access to hidden areas or to improve visibility of an area
- Determine the presence or absence of environmental or health concerns including, but not limited to: contaminated soil, potable water, radon, lead, UFFI, air quality, mould, mildew, carcinogens or other such hazard
- Operate components or assess utilities that are shut off, winterized, covered, do not respond to normal operating devices or otherwise restricted
- · Light pilot lights that are not in functioning order / Ignite or extinguish solid fuel fires
- Perform invasive procedures to investigate a potential defect in construction, for this reason the inspector will often recommend a specialist be brought in to further evaluate components.
- · Enter any area which the inspector feels is unsafe for entry, with headroom of less than 3 feet or areas with standing water
- · Inspect or evaluate the operation of any underground drainage pipes, footings, etc.
- · Operate air conditioning systems if the temperature has fallen below 16 degrees Celsius in the past 24 hours.
- · Inspect or evaluate items not permanently installed
- · Project operating costs of any components
- · Uniformity or adequacy of heat or cool supply to any rooms
- · Report on sizing or efficiency of heating or air conditioning units
- · Operate automatic safety controls
- · Report on anything not visible to the inspector, including but not limited to: concealed insulation or vapour barriers, inside walls, floors or ceiling cavities
- · Operate heat pump in heat mode when temperature has been above 22 degrees Celsius in the past 24 hours
- · Perform formal energy audit or evaluation
- · Report on property lines or encroachments
- · Evaluate or operate digital or computerized thermostats or controls
- Report on conformance or legality of secondary or basement apartments or finishings
- Determine if a building permit has been issued for any additions or renovations, etc.
- · Observe the interior of chimney flues, fire chambers, heat exchangers, humidifiers or filters
- · Report on the presence or absence of wood destroying insects
- · Make assurances of a dry basement or crawl space
- If building is covered by condominium management, determine which items are the responsibility of the condo or owner, we rely on the homeowner for this
 information

The Inspector is not required to:

- · Evaluate fountains, spas, swimming pools, septic, cisterns, water treatment systems etc.,
- Report on the cause of observed damage or recommend repair techniques or contractors
- Evaluate shower pans for leakage
- · Report on anything other than output from wells, the inspector shall run the water from inside to determine functional flow
- · Determine whether waste lines are municipal or private, and is often required to rely on the homeowner for this information
- · Test or operate any over current devices except Ground Fault Circuit Interrupters
- · Evaluate geological conditions, soil conditions, recreational facilities, or outbuildings other than primary garages and carports
- · Operate trash compactors, individual room and window cooling units or evaluate the effectiveness of anti-siphon devices
- · Test carbon monoxide detectors or smoke detectors by any means other than the test button
- · Evaluate clearances around heat sources

Acknowledgement: Each office is independently owned and operated. Acceptance and understanding of this Visual Pre-Inspection
Agreement is acknowledged. Receipt of a copy of the Pre-Inspection Agreement is also acknowledged. Inspector providing the home inspection service and Report
is an independently owned and operated business that has been granted license to use the Lighthouse inspections names, trademarks and methods. In retaining
this Inspector, the Client acknowledges that the Franchisor is not involved in the day-to-day activities and is in no way responsible for the Inspector's services or
actions. Any questions relating to this service should be directed to Inspector and his/her company.

100		04/64/16
Signature: Client or Client's Representative		Date
mbl I	Representative:	Michael Tita
Representative Signature	Company Name:	Elite Team Home Inspections Limited
	Operating as:	Lighthouse Inspections Mississauga East
	Address:	2325 Hurontario St. Suite 322, Mississauga
	Phone Number:	905-271-6381

Payment Information / Receipt

Fee, including inspection and report agreed to above and other services, (including HST) \$ 457.4

Payment received by (circle) Cash Cheque # _____

Cheque # _____ Visa / MC / Disc. Auth.

© Lighthouse Inspections
EACH OFFICE IS INDEPENDENTLY OWNED AND OPERATED

(E-Transfer

Lighthouse Home Inspection Report

The main purpose of the Lighthouse home inspection is to provide clients with a better understanding as to the general condition of the home. A visual inspection of the building and its immediate grounds has been conducted in accordance with the pre-inspection agreement and the standards of practice in the home inspection industry. The facing pages outline general information and the Lighthouse standard of practice. This information forms an integral component of the inspection results and should be reviewed thoroughly in conjunction with the personalized sections of the report. The home inspection report is confidential and was prepared for the exclusive use of the client as identified in the agreement.

Weather at start of inspection:	Address of Inspection: 235 Symi	ing ton	Are. Toronto	DE O
Weather at start of inspection:	Date of Inspection: Apr. 4/16	Approximate s	tart time: 7-75 (A.M. P.M. (circle) stop time 12	A.M. P.M.
Approximate outside temperature during the inspection	Recent WEATHER conditions:	ing	Rain past 3 days:YesL	_ightNo
Front of Building facing:NorthSouthEastWest In Attendance:ClientHomeownerOther General Accessibility:Excessive storageConstruction in progressSystems winterizedUtilities turned offOccupied room or sectionAccess deniedOther Reference: Item & Page Number General Structure & Roofing	Weather at start of inspection:	1, +/4	rries Ground Condition Wet_	_Dry_Snow
General Accessibility:Excessive storageConstruction in progressSystems winterizedUtilities turned offOccupied room or sectionAccess deniedOther	Approximate outside temperature during the inspe	ection5	C. & prior to inspection/O_C.	
	Front of Building facing:NorthSouth	East West	In Attendance:ClientHomeownerC	other
Reference: Item & Page Number General Structure & Roofing 4 Basement & Crawl Space Chimneys & Roof Drainage 6 Water Penetration & Internal Structure Vehicle Parking 8 Laundry & Wet Areas Exterior 10 Kitchen and Appliances	General Accessibility:Excessive storage	Constru	uction in progressSystems winterized	
General Structure & Roofing 4 Basement & Crawl Space Chimneys & Roof Drainage 6 Water Penetration & Internal Structure Vehicle Parking 8 Laundry & Wet Areas Exterior 10 Kitchen and Appliances	Utilities turned offOccupied room of	or section	Access deniedOther	
Chimneys & Roof Drainage 6 Water Penetration & Internal Structure Vehicle Parking 8 Laundry & Wet Areas Exterior 10 Kitchen and Appliances	Refere	ence: Item	& Page Number	
Vehicle Parking 8 Laundry & Wet Areas Exterior 10 Kitchen and Appliances	General Structure & Roofing	4	Basement & Crawl Space	22
Exterior 10 Kitchen and Appliances	Chimneys & Roof Drainage	6	Water Penetration & Internal Structure	24
	Vehicle Parking	8	Laundry & Wet Areas	26
Additions 12 Bathrooms	Exterior	10	Kitchen and Appliances	28
	Additions	12	Bathrooms	30
Grounds & Air Conditioning 14 Fireplaces & Common Safety Devices	Grounds & Air Conditioning	14	Fireplaces & Common Safety Devices	32
Electrical General Interior	Electrical	16	General Interior	34
Plumbing 18 Attic & Ventilation	Plumbing	18	Attic & Ventilation	36
Heating 20 Insulation	Heating	20	Insulation	38

Please note some deficiencies in the home may not be included on this summary page. Items that do not pose immediate safety hazards may be observed and omitted from this page.

The overall, general habitability of this home, taking into account the entire report, is in the opinion of the inspector:

If you have any questions, we encourage you to contact your inspector at

General Structure & Roofing

Building Style	Roofing
Detached Semi- Detached	Roof Style(s)GableShedHipFlatNansardGambrelRidgePitched
Townhouse Condominium / Apartment	Roof Covering(s)Asphalt Shingles Tar & Gravel Wood Shingles Metal Rolled Slate / Clay Tiles
Bungalow 2 Storey Split Level 2nd floor extends out beyond 1st floor	Estimated life span:YoungerMid-lifeOlder or End of useful life Number of layers
Estimated Age:Under 10 years10-2525-6060+over 70 years	Inspection Method: From ground with binoculars from a window from roof edge
Occupancy:OccupiedVacant General Construction:Wood FrameMasonry	Identified the following conditions: lifting / clawing / cupping / curlingbubblingdirtyparticulate releasingdried, brittle / crumblingbroken / missing partsother roof covering deteriorationexcessive moss or mold growing on roofwaves and dips noted between structural members, see ATTIC
Flashing MaterialNone notedunknown metalRubberized membraneGalvanizedMaterial not determined Defects:Appears to be patchedPieces damaged / loosePieces missingFrom interior, stains or wet spots indicate possible leaking at or near flashing	Section of report Younger roof covering indicators:cleanfresh colourlaying smooth Inspection Limitations: Theportion of roof was not visible to the inspector and should be inspected by a roofing contractor to determine condition
Course of Action:	Roofing is mostly snow covered Flat roof is covered by decking and could not be inspected Leaks see Moisture and water penetration in ATTIC section of report.
Skylights & Roof Windows None noted on exterior of house # of units noted Type: Domed Flush Roof Curb identified	Course of Action Recommend roofing contractor reroof Recommend roofer
Material:glassplasticunknown materialPatching noted around unit on roofEvidence of condensation noted Caulking around unit:appears adequatemissing or damaged, recommend repair Defects noted:Cracked Glazing:double or triplesingle, requires repair Skylights and Roof Windows are also identified on Interior section of report.	Soffit & Fascia Soffit:aluminumwoodplasticPaintedPaint deterioratedMouldRottedlooseevidence of leaksrustcorrosion Fascia:aluminumwoodplasticPaintedPaint deterioratedMouldRottedlooseevidence of leaksrustcorrosion
or report.	

Course of Action: Have a roofing or other appropriate contractor repair any deficiencies noted above.

Chimneys & Roof Drainage

Chimney	Drainage
BrickBlockStoneMetal	Nothing noted to direct roof run off
Chimney is covered, limiting inspection	On roof diverters were noted
Clearance sufficient above roof	
Chimney saddle on roof above chimney Number of chimney(s)	Gutters and Downspouts
High Efficiency exhaust	Cutters and Downspouts
Missing or loose mortarCracks	Material:AluminumCopperPlasticOther metal
Flue linerobservedcrackedmissing	Defects:
Olemand, Inc. del	LooseBrokenOut of adjustment
Clean-out: locatedUnable to operate, have repaired	Remove debris which is sticking out of systemStains over outer gutter edge indicate overflow, system may be
Clean-outDirtyDamagedBlocked	clogged or undersized
Chimney cap / washobserved Broken / damaged	Lasking observed at:
Cap overhanging to protect brick None noted	Leaking observed at:DrainsDownspoutsCorners of gutters
Rain Cap / Spark ArresterNone noted	
add as needed	Discharge:
Defects Observed.	Discharges onto ground
CrackedLooseDamaged	Discharge extended 6 feet from foundation
Deterioratednot visible	Discharges into pipe or hole in ground
Flashing at chimney secure	Did Did not determine where pipe exits
LooseDamaged, repair / reseal / replace	Recommend change to ground discharge
BEFORE USE, have chimney sweep clean, further evaluate &	Sufficient number of downspouts
repair as needed.	Add downspout at:FrontRearLeftRight side
Temporary / non-standard repair observed, recommend	Downspouts blocked
mason evaluate and repair as needed.	
Course of Actions	Gutters:
Course of Action:	RustyHolding water (adjust)Clean gutters
Exterior Ventilation	
Types:Gable End VentsRidge VentSoffit Vent	Course of Action:
WindowsAttic fan(s)Roof ventsTurbinesSelf opening & closing louvered vents.	Recommend add / adjust splash blocks Recommend add extensions to downspouts to direct water
Sell operalling & closing louvered vertis.	farther away from foundation
Side Walls:	Recommend redirect water discharge off lower roof – connect
No evidence noted to indicate need to increase ventilation	with lower gutters or direct to ground discharge
Spalling brickMould/mildew spores	
Peeling or stained paint on exterior siding seems to indicate more	Downspout missing, re-install
rentilation is needed in side walls for the house to breathe better	Water penetration noted, make appropriate repairs
	Have the appropriate type of contractor make repairs as needed
Course of Action:	to the above components
Recommend adding ventilation	
Additional Comments or Issues:	

Course of Action: Have a roofing, masonry, or other appropriate contractor evaluate and repair as needed.

Vehicle Parking

None notedAsphaltConcreteStone of gravel	Mone Noted Garage
Defects noted:	Estimated Size: Car(s) Bays are: side by side tandem Attached living space above Semi-detached Detached Interior accessed: Yes No because Visibility limited by: Parked car Storage Floor: Concrete Asphalt Dirt normal condition Defects: Cracks Depressions Oil stained Deteriorated surfaces
Other Parking Area None noted Not determined On street Off street Common parking area	Walls:MasonryWood framed Framingexposed to viewblocked by storage / walls finishedExterior finishes deteriorated, replace Automobile doors:Overhead Swinging Number:such doorsOperatedNot-operated, because
Carport None Noted Size:Car(s)AttachedSemi-detachedDetachedVisibility clearVisibility obstructed by:Parked carStorage Floor:ConcreteAsphaltDirtNormal conditionDefects:CracksDepressionsOil StainedDeteriorate surfaces Walls:Vertical supports onlyOpen to weatherEnclosed on #sides Roof underside:Framing and sheathing exposed to view from insideStored items restrict viewing Water Penetration:Water stainsWater leaking throughDamaged members Attic:Enclosed attic:AccessNo access EnteredYesNo Course of Action:	Electric opener noted operated not operated, because Applied resistance and door did did not stop or reverse, as expected Adjust sensor Missing safety cables inside of overhead garage doors springs, have contractor install. Man doors: into house to exterior # doors operated Requires proper step(s) Self Closing door? Yes No Add Not operated, because Results: Windows: None fixed operational Not tested, because Results: Results:

Course of Action: Have a home improvement or other appropriate contractor evaluate and repair as needed.

Exterior

Wall Finishes	Foundation Walls
Location:AllMain FloorUpper floor Front RearSide Brick / Masonry Wood Aluminum/Vinyl Stucco Cement board EIFS (Exterior Insulation and Finish System) Evidence of Condensation present Yes No General Condition Typical deteriorated Repairs Required Location: All Main Floor Upper floor Front Rear Side Brick / Masonry Wood Aluminum/Vinyl Stucco Cement board EIFS Evidence of Condensation present Yes No	Poured ConcreteBlock & MortarStone & MortarBrick & MortarWoodStucco over unknown Defects:Cracks observed were smaller, monitor over timeLarger cracks were observed, recommend repairVines, shrubs, trees or other planting obscuring the view of the foundation. These plantings will restrict the inspection scope and may be hiding significant defects.
General ConditionTypicaldeterioratedRepairs Required Finish too close to grade, repairVines, shrubs, trees or other planting obscuring the view of the wall finish. These plantings will restrict the inspection	Structural No major structural defect evidence was noted, appears in normal condition for its age Major structural defect evidence was noted, as described: Course of Action:
Windows Normal condition for age of houseUpgradedStormsScreensSome may be missingLoose or missing glazing should be replacedLoose or missing caulk, have recaulked Trim, Observed:MouldDecay / rotRe-seal sills	SolidHollow coreFrench doorsSliding glass MetalWoodfiberglass / composite Open & close as expected Need adjustments to operate as expected Broken door or parts need repairing/replacing Missing/broken hardware to be installed/replaced/repaired. Reseal frames Storm doors Operated:open & close as expected Doors require adjustment to operate as expected Trim, Observed:MouldDecay / rot
Window Wells None notedNone notedNoneConcrete UncoveredCovered UncoveredCovered Defects:BrokenCrackedCrumblingFloodedDamaged coverWater Stains inside windows indicating poor drainage Course of Action:Recommend adding well for drainageCover should be installed/repaired to keep water outClose down openings for safetyRe-secure to wallGrade in well too high, lower	
Additional Comments or Issues: reseal former exhaust properly (rear wall)	point

Course of Action: Have an engineer, Pest Control or other appropriate contractor rectify any deficiencies noted above

Additions

Main Entry	Deck and Balcony
Location:concretePorch ofwoodconcrete	None noted
ConcretePorch ofwoodconcrete	Location: rear yard
stone with stepswalls enclose area	WoodMetalConcrete
Deteriorated/damaged steps / supports pose safety hazard	4
#steps down from porch	# Steps to grade
Step rise(s) too high / uneven, adjust	Too close to grade to look under
Handarila la madraila.	Close to grade could only see under some sections
Handrails/guardrails:	Sufficiently above grade to get under and look
None notedRecommend add for safety Loose or unsafe, recommend repair for safety	No access below: Blocked byStored itemsPlant growthElements(Snow, ice, water)
Loose of unsale, recommend repair for salety	Defects:
Wallarere	Uneven surfaces pose a trip hazard
Walkways	
None noted	No bolts noted to attach to house Bolt to framing Install missing / additional joist supports
To Main entry:ConcreteAsphaltPavers	Support columns not attached to foundation
Slate Gravel Interlock / brick	Take steps to reduce sway or deflection noted
Uneven/broken surfaces pose trip hazard	Wooden piles / supports below soil, raise above soil level
	Wood flooring and/or structure deteriorated
Other walks Concrete Asphalt Pavers	Improve supports as required
SlateGravelInterlock / brick Uneven/broken surfaces pose trip hazard	Handrails/guardrails:
Oneversoroken surfaces pose trip nazara	None noted Recommend add for safety
	Feel loose Broken Close down openings for safety
Secondary Entry	
None noted	
Location: rear yard	
Location:	Patio
Concrete slab Porch of wood concrete	None noted
stone with stepswalls enclose area	rear une
Deteriorated/damaged steps / supports pose safety hazard	Location: rear yard
#steps down from porch	ConcretePaversSlateStoneInterlock
Step rise(s) too high / uneven, adjust	Uneven/broken surfaces noted which pose trip hazard
Exterior below grade entry notedrequires proper step(s)	
Requires proper drain	
	Retaining Walls
Handrails/guardrails:	None noted / decorative only
None notedRecommend add for safety	Wooden:Pressure treated
Loose or unsafe, recommend repair for safety	Unknown if pressure treatedAppear untreated
	ConcreteBlockStoneBrick
Fences	Mortar joints observed
	Drainage holes to relieve water pressure from behind the wall
Wood Metal Other	areare not evident.
> secure	Defects:
loose weak Broken sections	BucklingBowingCrackingLeaning
Gate: operated self-closer install self-closer	Other displacement
X Inspector does not know ownership	
Additional Comments or Issues:	
radicional comments of 133063.	

Course of Action: Have the above noted deficiencies corrected by the appropriate contractor

Grounds & Air Conditioning

Grading	Air Conditioning
Within 6 feet of foundation:	None Noted
Front of house, slopes	Location: front
towardaway from houseis relatively level,	Location: Trok+
Right of house, slopes	Brand name on central unit:
towardaway from houseis relatively level Left of house, slopes	Brand name on central unit:
towardaway from house is relatively level	Type: Central Air Heat Pump Gas Chiller
Rear of house, slopes	Evaporative Cooler Electric Compressor
towardaway from houseis relatively level.	Roof or attic mounted (or other) system
Beyond 6 feet.	Ductless Air Conditioning system
Entire lot is relatively level	Water cooling system, recommend replace
Slopes away from house, acceptable	
Slopes towards the house, should be graded away	
X Recommend grading slope to direct water a minimum of 6 feet	In use during inspectionOperated
rom foundation to minimize water penetration	
1	Not operated
General grading should be addressed as larger depressions	(see opposite page for testing limitations)
can pose a trip hazard	
Ravine lot, potential erosion concerns	
Recommend the following negative effect on the building is	
ddressed:	Visible portion of equipment appears to be
	NewerMidlifeOlder
General grading could not be assessed due to snow.	or ApproximatelyYears old
	~
Trees, Shrubs, & Plantings	Central unit appearslevelnot level
rees, shrubs and other plantings near the home should allow the	Outdoor fan is:obstructed
ome to breathe	Outdoor grills are:damageddirty
None noted near house which appear to pose a possible	Have all debris removed before use
nazard to the house at the present time.	Compressor isnoisy
Planting(s) noted overhanging / touching /near to / climbing on	
ouse	Ductwork
hese conditions should be corrected, usually involving cutting back,	in common with heatingindependent from heating
oruning or removal of the planting.	
Other plantings, away from house, should be inspected by	
lient and attended to as needed	With unit running, house seemed to cool
	slowlyquicklyadequately not at all
Environmental	
Although not required as part of a Home Inspection, some evidence	Course of Action
oticed by an inspector, which might indicate some environmental	
azard, chemical or oil spills:	
Dead foliage, out of season - looks unusual	
Dark stains on soil Oil slick or stain on water	Individual room units observed
bandonedmotor vehicle(s)batteriesPaint cans	operatednot operated
Pipes into the ground may indicate buried storage tanks	Results:received coolingdid not receive cooling
Out of use storage tanks	
Although none was detected, homes of this era may have	Course of Action
dditional environmental hazards/concerns.(i.e., lead, asbestos, etc.)	
Course of Action:	
Recommend further evaluation by an appropriate contractor	
before any renovations of the property.	

Course of Action: Have a heating / cooling or landscaping contractor evaluate and repair as needed.

Electrical

Distribution Outlets, switches, lighting as observed and evaluated, throughout the home. Random tested outlets, wall switches & installed lighting and found the following evidence: no deficiencies were detected 3 holes(Says grounded) Outlets with 2 slots (Older ungrounded style) Material Copper Aluminum Knob & Tube Pleases note that Aluminum and/or Knob and Tube wring may exist within the homes' system and not be visible to the inspector or reported due to the limited homes' system and not be visible to the inspector or reported due to the limited homes' system and not be visible to the inspector or reported due to the limited homes' system and not be visible to the inspector or reported due to the limited homes' system and not be visible to the inspector or reported due to the limited homes' system and not be visible to the inspector or reported due to the limited homes' system and not be visible to the inspector or reported due to the limited homes' system and not be visible to the inspector or reported due to the limited homes' system and not be visible to the inspector or reported due to the limited homes' system and not be visible to the inspector or reported due to the limited homes' system and not be visible to the inspector or reported due to the limited homes' system and not be visible to the inspector or reported due to the limited homes' system and not be visible to the inspector or reported due to the limited homes' system and not be visible to the inspector or reported due to the limited homes' system and not be visible to the inspector or reported due to a circuit protector, have evaluated for safety by electrician Abandoned wire(s) Copen ground Open neutral Open hot determine percentage of older wiring. Defects: Ungrounded outlets Geversed Dead outlets Open ground Open neutral Open hot determine percentage of older wiring. Defects: More than one wire attached to a circuit protector, have evaluated for safety by electrician Abandoned wire(s) Connections in panel box Non-standard in	Main Service Entrance	Main Distribution Panel
Outlets, switches, lighting as observed and evaluated, throughout the home. Random tested outlets, wall switches & installed lighting and found the following evidence:	Service Line:UndergroundOverhead wires Overhead Contact Hazards observed:obstructed / threatened / touched by tree / branches have hydro or a tree surgeon correct situation before damage occurs Meter Service cable rated:Amps Rated110/120 Volts220/240 VoltsW (# wires in service)	Service Panel Rated Amps Main Disconnect: Amps Circuit breaker Fuses Knife switch Location Main panel box Other Service Size Amps Circuit Breaker Fuses 110-120 volt circuits: (number) 15A 20A 30A 220-240 volt circuits: (number)
Outlets, switches, lighting as observed and evaluated, throughout the home. Random tested outlets, wall switches & installed lighting and found the following evidence:	Distribution	
Hot Ground reversed Dead outlets Open ground Open neutral Open hot Missing safety covers on switches, outlets and junction boxes Loose connections Loose boxes Loose receptacles Lights did not light, missing or broken bulbs Flickering lights Switches for which use not determined (frequently noted) Loose hanging wires / otherwise dangerous conditions. Bare bulbs near / touching storage items, possible fire hazard Move wires off heating ducts (secure) Lighting at staircases is not sufficient In staircases with 3 or more steps, switches are not located at both the top and bottom of staircase. Decora style switches and outlets noted throughout system, have checked for proper installation with aluminum wiring Have an electrician check entire system and rectify deficiencies as needed. ESA certificate may be recommended or required due to a circuit protector, have evaluated for safety by electrician Abandoned wire(s) Connections in panel box Non-standard installation / upgrade, further evaluation Water stains Rust Dead insects, may indicate cable entry not sealed properly Unprotected panel openings, recommend closing down Overloaded circuits Loose connections into the box within the box Damaged sheathing Overfused breakers / fuses Discoloration of wires in panel, may indicate overloaded circuits Discoloration non-conforming, needs to be addressed Course of Action. Have an electrician install Arc Fault Interrupter (AFCI)	Outlets, switches, lighting as observed and evaluated, throughout the home. Random tested outlets, wall switches & installed lighting and found the following evidence: no deficiencies were detected3 holes(Says grounded)Outlets with 2 slots (Older ungrounded style) Material CopperAluminumKnob & Tube *Please note that Aluminum and/or Knob and Tube wiring may exist within the homes' system and not be visible to the inspector or reported due to the limited nature of such an inspection. Inspector cannot determine percentage of older wiring. Defects:	CopperAluminumKnob & TubeBX Cable (Metallic sheathed)Romex (Non-metallic sheathed)Not determined As observed:inside panel box Circuits labeled?YesNoSome Panel has been upgraded from original Sub PanelsNone noted# noted, Panel RatedAmps; Service SizeAmps
Missing safety covers on switches, outlets and junction boxes Loose connections Loose boxes Loose receptacles Lights did not light, missing or broken bulbs Switches for which use not determined (frequently noted) Loose hanging wires / otherwise dangerous conditions. Bare bulbs near / touching storage items, possible fire hazard Move wires off heating ducts (secure) Lighting at staircases is not sufficient In staircases with 3 or more steps, switches are not located at both the top and bottom of staircase. Decora style switches and outlets noted throughout system, have checked for proper installation with aluminum wiring Have an electrician check entire system and rectify deficiencies as needed. ESA certificate may be recommended or required due to aluminum or knob and tube wiring evaluated for safety by electrician Abandoned wire(s) Connections in panel box Non-standard installation / upgrade, further evaluation Water stains Rust Dead insects, may indicate cable entry not sealed properly Unprotected panel openings, recommend closing down Overloaded circuits Loose connections in panel box Non-standard installation / upgrade, further evaluation Water stains Rust Dead insects, may indicate cable entry not sealed properly Unprotected panel openings, recommend closing down Overloaded circuits Loose connections Discoloration of wires in panel, may indicate overloaded circuits Discoloration of wires in panel, may indicate overloaded circuits Course of Action. Have an electrician install Arc Fault Interrupter (AFCI)		Defects:
	Missing safety covers on switches, outlets and junction boxes Loose connections Loose boxes Lights did not light, missing or broken bulbs Switches for which use not determined (frequently noted) Loose hanging wires / otherwise dangerous conditions. Bare bulbs near / touching storage items, possible fire hazard Move wires off heating ducts (secure) Lighting at staircases is not sufficient In staircases with 3 or more steps, switches are not located at both the top and bottom of staircase. Decora style switches and outlets noted throughout system, have checked for proper installation with aluminum wiring Have an electrician check entire system and rectify deficiencies as needed. ESA certificate may be recommended or required due to aluminum or knob and tube wiring	evaluated for safety by electrician Abandoned wire(s)Connections in panel boxNon-standard installation / upgrade, further evaluationWater stainsRustDead insects, may indicate cable entry not sealed properlyUnprotected panel openings, recommend closing downOverloaded circuitsLoose connectionsinto the boxwithin the boxDamaged sheathingOverfused breakers / fusesDiscoloration of wires in panel, may indicate overloaded circuitsPanel location non-conforming, needs to be addressed Course of Action:Have an electrician install Arc Fault Interrupter (AFCI)
General Limitations protection	General Limitations	protection
X Concealed electrical components cannot be inspected Main disconnect cover could not be removed, common Panel cover could not be removed due to accessibility, recommend correct Power off insomeall areas No access to: In most cases, grounding termination point is not visible. Panel may be overloaded, have evaluated and repaired as needed Have an electrician check panel and rectify deficiencies as needed.	Main disconnect cover could not be removed, common Panel cover could not be removed due to accessibility, recommend correct Power off insomeall areas No access to:	needed Have an electrician check panel and rectify deficiencies as
Additional Comments or Issues:		

Course of Action: Have an electrician evaluate and repair entire system as required

Plumbing

Water Supply Entry Location Basement Public Meter Location Basement Private	Pipes:ABS PlasticCast IronCopperLead
Public Meter LocationBasement Private	Pipes:ABS PlasticCast IronCopperLead
Private	
Private	Galvanized SteelBrassNot Visible
	Pipes observed under 5/n/s
ocation of wellhead	Main waste line clean-outswere _>_were not observed
	Cheater vent(s) noted
Main Shutoff valve: at entry	Ventingwaswas not observed extending through roof
	and waswas not seen in attic
Supply Pipes:CopperPlasticGalvanized BrassLeadCould not determine	"S' traps noted in drainage system, should be rectified No 'P' traps visible
Conditions requiring attention:	Conditions requiring attention:
	Leaks in waste system:
Distribution Pipes:PlasticGalvanized	None notedactive leaksdry leak type stains
BrassLeadUnknown metal	were observed
Conditions requiring attention:	Odour noted at, have evaluated b
	plumber
V.	Discharge
Leaks in water supply systemNone noted	PublicPrivate
Rust / Corrosion noted	Reported byVendorRealtorNot Determined
Anterchant of South	Drain line exits at
Hose Bibs	
Number 2 Noted	Waste Ejectors
When turned on water came out, when turned off the	None Noted
	Drain or waste ejector pumps were observed
waterdiddid not shut off fully.	
When turned on water did not come out	Location
Not tested, because	When water was run the pump(s)did did not
nterior:	seem to pump out the waterSlow drainage was noted.
Hose bib shut off valve(s) located	Change ejector pipe to PVC/ABS
Did not locate at, locate and leave accessible	
Frost protected, interior shutoff may not be required	Domestic Water Heater
	Location basement
	Rental Owned unknown
Functional Flow	
Not Tested because	Estimated age / year(20/0)
	Estimated age / year
Method: With multiple fixtures running, flushed toilet(s)	Gas Electric Oil Propane
o over stress flow, observed decrease in flow:	Water on Demand systemIntegral with heating system
minimal acceptable excessive	Rated Capacity / 5 / gallons / Liters, which is generally
	ample for aboutpeople, depending on usage.
Hot Water Output:	Safety pressure release valvewaswas not observed
	and did did not have safety extension down to floor.
	No Some Extensive rust / corrosion / water
which were operated, in random testing, indicating the system	noted at base of unit indicates unit is leaking.
is not providing hot water to these faucets.	noted at base of unit indicates unit is leaving.
After aboutminutes of running hot water at	Work Direc Wildred School and allow to the beautiful to
2 4 4/r sink faucet, water coming from faucet was	Vent Pipe:doesdoes not slope or rise to exhaust
hotcold.	pipe looseconnection(s) loose
	rusted or deteriorated (rengin)
	joint to exhaust in need of repair
	, Y
Additional Comments or Issues:	
CONTROL OF THE CONTRO	

Course of Action: Have a plumber or other appropriate contractor repair / replace items noted as needed.

Heating

General Heating System	Distribution
Fuel:	Ductwork / RegistersUnobserved Radiant
Gas Oil Electric Wood Propane	Baseboard heaters Thermostat(s)on unitson wall
Type:	Radiators Bleed valves Leaks / Corrosion
Forced Air Electric Baseboard Electric Radiant	Heat equal at both ends, indicates proper distribution within unit
Hot Water Radiant Boiler Steam Boiler Geothermal	Boiler system: pressure release valve extension missing
High efficiency mid-efficiency low efficiency	Heat supply & return PIPES:
Integral with water heater / water on demand system	Copper Galvanized Iron Plastic Unknown material
Approximate age/year of systemas evidenced by:	Observed in: basement crawlspace attic
Serial #	some most pipes not visible
Brand Name: Notatune	Heat Distribution: was was not found in each room – add as needed
Furnace not operated due to temperature (see opposite page	was was not found in each room – add as needed
for testing limitations)	Distribution missing from: rear bedroom
RecommendServiceClean Furnace	Heat Recovery Ventilator (HRV) noted:working properly
Remove filler pipes for previous heating system	Recommend maintenanceRecommend service
Improve clearance around furnace for safety and access	Course of Action:
Previous oil tank noted Oil line noted below surface,	Clean Ducts
recommend further evaluation. Estimated age of oil tank Add vent to furnace room	Insulation on heating pipes/vents, recommend test for asbestos Seal gaps/joints at ductwork and plenum to maximize the
Corrosion/rust/water noted in furnace, evaluate and repair	efficiency of distribution system.
	emotor of distribution system.
Controls	
Heating System was was not in use during inspection	Heat Exchanger
Thermostat(s) were locatedmain floor	Heat exchanger is hidden from view, inside the unit, and therefore
The system seems to be regulated by individual controls	cannot be inspected.
in each heated areaon the heating units themselves	The following evidence suggests that the heat exchanger may be defective
When turned on by above thermostat(s)/control(s), units fired or gave heatdid not fire or give heat.	De delective
HRV control (s) located in	Filhaus
	Filters
A furnace electrical disconnect notedabovethe unit	Air Filter in warm air heating/cooling unit. Washable Disposable Electronic HEPA
An automatic Shut-Off Safety Device(s) was noted on the oil line attankburner	Location at furnace in return grill
on the on line attankburner	Not installed properly to correctly filter air
A CONTROL AND A	None noted, have it located and evaluated or have installed
Energy Supply	
Gas, believed to be publicElectricity	by heating contractor.
Oil tank in basementFill pipes indicate possible buried oil tank	Heating contractor should rectify defects.
Gas, onsite, evidenced by white storage tank	Recommend non-allergy type filter Filter appears clogged/blocked replace/clean
Entry Location Gas meter location appears too close to vent/A/C, have checked	Filter appears clogged/blocked replace/clean
by HVAC technician Bond gas line to proper ground	Oil Line Filter:
Fuel Leaks noted? No Yes	Locatednear entry into basementnear oil tanknear furnace
Flue Pipes	Oil filters should be serviced by a heating contractor annually
Flue pipes were identified	along with the oil heating unit.
Do Do not rise slightly to chimney / exhaust	Humidifier
	0.42331545555
Joints appear looseRusted or deteriorated Connection to exhaust is loose or in need of repair	None notedheating duct
Pipes too close to combustibles, recommend repair	Filter appears cleanAdjust water level
	Working Not working Disconnected
Supplemental Heat	
None noted Some noted	Parts Missinghumidifier should be replacedDrum type humidifier, recommend replace with drip type
Type, Location, and operation:	Humidistat Located:
-	Tomostat cooles.
Additional Comments or Issues	
Additional Comments or Issues:	

Course of Action: Have a heating contractor rectify any defects noted above.

Basement & Crawl Space

100 Percent of lowest level	None noted Percent of lowest level
Exterior access / egressNone notedDirect walk outUp exterior stairway bulkhead	AccessibleNot AccessibleNot EnteredNot Entered, because
Foundation walls:CoveredVisible Approximate percentage visible	Floors:concretedirt Ventilation:notednone noted Type:wall ventsvents into basement Insulation observed:YesNo; Adequate?YesNo Vapour Barrier:on warm side of insulationNone notedInstalled improperly Moisture Evidence:PresentNot noted Water Penetration Evidence:notednone noted
Evidence ofPreviousActive leak Defects noted: Settlement cracksMinorMonitor over time Significant, have a mason repair Have cracks / leaky areas repaired to prevent ongoing leakage	Slab on Grade Not ApplicablePercent of lowest levelconcretewoodunknown / not visible slab:at about grade levelslightly above/below grade The support system below grade is not observed and is unknown. The exterior perimeter of the slab, where visible, cracks
Basement Ceilings Exposed to view Hidden from view Partial view Ceilings finished? Yes No Evidence of Previous Active leak	werewere not notedNo areas visible Exposed interior floor coverings are of:concrete vinyl wall to wall carpethardwoodsoftwood carpet less than wall to wall in coverage Observedbrokenwarpedrippled floor coverings, which may indicate cracks in the slab.
Basement Floors concretedirt Covered withtile sheet goodscarpetingpainted Hardwood / softwood / laminated wood	Support Columns Not Applicable Support columns ofMetalConcreteWoodStoneBlockBrick
	were observed under the Support columns condition looked Satisfactory
Satisfactory Defects:Settlement Cracks in floor were noted which appear to be:neweroldersmall, probably not major defects at this time, which should be monitored over time to see if they worsen larger major defectsshowing differential settlement heaving	Floor Drainage Floor Drainage observed: Yes No did did not have protective perforated cover Trap primer noted? Yes No Evidence of trap cracked / broken Recommend install backflow preventer
	Cold Room Not Applicable Install/replace weatherstripping at door Venting installed venting blocked, open and leave active No venting, proper venting to be added It is not recommended to finish or partially finish a cold room.

Course of Action: Have a masonry or other appropriate contractor repair the above items as indicated.

Water Penetration & Internal Structure

Water Penetration	Basement Structure
No signs noted	Joists
Evidence indicates a one time flooding	Not visible
Some extensive evidence of ongoing water penetration	Steel
was observed	Condition and defeats asked and halous
Evidence observed: Water stains on:	Condition good defects noted, see below
vvater stains on:	Span and beams appear adequate Defects Observed:
On walls, at base of wall floors	Cracks / cuts that reduce effectiveness, repair
base of stairs around furnace Efflorescence Rot	Joists span too large, add additional support
Microbial growth / mildew	Rot on joists has reduced strength, repair
Rust on nail heads/ baseboard heaters, etc.	Evidence of sagging floors that is,
Sump pump, see section	Minor / older, monitor over time for changes
Wall board damaged	Movement appears to be recent and/ or ongoing, add
Damp or wet floor coverings	additional supports
Lifting tile	Add (#)joist hanger(s)
Other	0-1
Limitations to inspection:	Columns Not visible
Limitations to inspection: Subfloor & carpet Storage Furniture	
Subilibor & carpetStorager uniture	Appears to have been altered/removed have evaluated
Course of Action:	Condition:
Overall, stains indicate previous flooding	Columns appear sufficient and in good condition
Further evaluation necessary	Columns appear to have shifted, repair immediately
Repair current leak issues noted	Defects observed:
Further evaluation and testing for possible mould recommended	Rot
(and remediation work performed as required)	Cracks have reduced strength, add additional support
General Dampness	Insect infestation appears to have compromised columns,
A second	repair immediately
None noted	
Feels dampSmells damp	Sump Pump
Dehumidifier noted	None noted
Location:	Location:
Dehumidifier was running during inspection	submersiblepedestal
Evidence that dehumidifier running continuously	Running continuously
Recommend use of dehumidifier in basement	Activated Not working
	Could not test unit No water in the hole
Basement Ventilation	The state of the s
Nonecontrol	Not plugged in (Electrical)
None noted	Recommend backup system or alarm Operating properly Slow Replace
Type:	Operating propertySlowReplace
Louvered wall vents	Discharge
Window S	Exterior Storm drain Unknown Sewer connection
Area open to main and / or upper floors (open stairwell)	
Exhaust fan	Course of Action:
Air Exchanging unit	repair/replace
Other	install sump pump
2	Redirect discharge
Course of Action: Add additional ventilation to reduce condensation / moist air	install check valve
Aud additional vehiclation to feduce condensation / moist air	
Additional Comments or Issues:	
Additional Collinions of 155465.	
A ** *********************************	

Course of Action: All defects noted above should be corrected and/or monitored by an appropriate contractor

Laundry & Wet Areas

Laundry Area	Laundry Tub
No laundry provisions noted Location:BasementMain floorUpper floorIn/near bedroomsIn bathroomIn/near kitchen	Tub Porcelain Steel Plastic Concrete Tub damaged / cracked, replace
Appliances: Laundry Clothes Washer None noted Brand Age: Newer Older Midlife Connections for water & drain were noted Connections not visible Condition of water hoses: Satisfactory Replace Electrical Outlet Grounded Not grounded Replace outlet	Faucets: Faucets hot and cold working properly Faucets do not shut off fully Hot and cold reversed, have a plumber repair Drain securenot secure No leaks notedbelow tub Leaks at water lines
In use during inspection, performing normal cycles Operated one cycle, heard water come in, splash, spin and pump out Not operated Course of Action: Have an appliance repair contractor repair noted defects. Clothes Dryer None noted Brand None noted	Wet Areas None noted Location: Wet barAdditional sink onlyOther SinkPorcelainSteelPlasticConcrete
	CopperPlasticCast IronLeadSalvanized Steel Leaks notedNone notedAbove the sinkbelow the sinkAt taps Counter topPlastic LaminateCeramic TileWoodareare not secureloose (unsafe)missinglarge areas heat scorched or damaged Stored items affecting visibility of counter tops at time of inspectionminimalabout normalextensive
Electrical: Laundry	Electrical: Wet Areas
Ground Fault Interrupter None Noted Recommend add GFI's for safety	Ground Fault InterrupterNone Noted Recommend add GFI's for safety

Course of Action: Have an appliance, plumber or other appropriate contractor evaluate and repair as needed.

Page 26 of 38

Kitchen & Appliances

Location BasementMain floorUpper floor	Brand:Range / Cooktop Style:Free StandingBuilt in
Cabinets WoodenPlastic LaminateOther Cabinetsareare not secureend of life	Fuel type:ElectricGasOther Age:NewerOlderMidlifeNot operated
Doors and drawers:function as expectedloose cabinetsmissing hardwaremissing door or drawer frontsbroken drawerswarped doorsadjust doors Stored items affecting visibility as to condition at time of inspection were:MinimalNormalExtensive	In use during inspection, indicating portion being used is performing its major functionOperated and found that # burners gave heat and #did not give heat
Counter Tops	Brand: I Kea Oven D0043/935
Plastic LaminateCeramic TileGranite/Marble/Corianareare not secureloose (unsafe)missinglarge areas heat scorched or damaged Stored items affecting visibility of counter tops at time of	Part of the stove Built in Fuel Type: Electric Gas Self cleaning(Not checked) Age: Newer Older Midlife See Stove Not operated,
inspectionminimalabout normalextensive	In use during inspection, indicating the portion being used is performing its major function
Stainless SteelPorcelainPlastic Undetermined material	Bake and broildiddid not give heat when turned on.
Ran the water and found leaksNone notedAbove the sinkbelow the sink Have leaks repaired by plumber Sink chipped/cracked. Stopper/strainer waswas not noted	Brand: Refrigerator
None noted Brand horsepower Leaks noted? Yes No Have leaks repaired by plumber Tested unit, results:	Not operatedItems in cooling section felt cool, in freezer section felt frozen -indicates doing major functions Features:lce makerWater & Ice through doorFrost Free Magnetic Seal:Damaged / Broken
Ventilation	Dishwasher F C47002
None Noted, other than doors and windows Fan integral with a built-in Microwave or cooktop Exhaust fan appears to vent to exterior Recirculates air within the roomLight When the components were turned on, they seemed to perform their major function. Fan sounds excessively noisy Filters:ObservedNone Noted	Brand: Age:NewerOlderMidlife OperatedIn use during inspection Not operateditems/storage in machine HeardDid not hear water come in, splash and pump out, indicating that the appliance is doing its major functions Recommend relocate drain to sink side of P trap Recommend secure unit
Electrical	None noted Built in Microwave
Ground Fault InterrupterNone NotedRecommend add GFI's for safetyat sinkInadequate number of electrical outlets	Brand:
Kitchen Floor LaminateVinyl TileCeramic Tile WoodCarpet	Other Appliance
Normal amount of bounceexcessive bounce notedHave a flooring contractor correct any defects or deficiencies noted in floor.	Brand:OperatedNot Operated

Course of Action: Have an appliance repair or other appropriate contractor repair any deficiencies noted above.

Bathrooms

BATHROOM 1: Full Partial	BATHROOM 2: Full Partial
BATHROOM 1: Full Partial Location 695e meh	BATHROOM 2: 2 nd Full Partial
Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic	Tub:Built inLeg TubNone noted
Tub:Built inLeg TubNone noted	Tub;Built iiiLeg TubNone noted
Shower: with Tub Stall (reseal)	Shower:with TubStall Enclosure:PlasticCeramiccur+ain
Enclosure: Plastic Ceramic	Enclosure: Plastic Ceramic
Seems adequately fastened to wallYes No	Seems adequately fastened to wallYes No
Missing/damaged grout Evidence of moisture behind tiles	Missing/damaged grout Evidence of moisture behind tiles
Sink(s): #/ > VanityWall HungPedestal	Sink(s): #_/ > VanityWall HungPedestal
Feels adequately fastened Yes No	Feels adequately fastened Yes No
Tellet School Feelenderustely essured Ves	Tailet: Chahed Feels adequately secured Vos No
Toilet: Flushed, Feels adequately securedYesNo	Toilet: Flushed, Feels adequately secured Yes No
Bidet: None notedTurned on resecure	Bidet: None notedTurned on
Feels adequately fastenedYesNo_Foi lest	Feels adequately fastenedYesNo
Damage:None NotedCracked / Chipped	Damage:None NotedCracked / Chipped Noted at TubShowerSinkBidet Taps
Noted at Tub Shower Sink Bidet Taps	Noted at Tub Shower Sink Bidet Taps
Floor:VinylCeramic Tile	Floor:VinylCeramic Tile
Soft or weak spots noted in floor	Soft or weak spots noted in floor
	Vents: Window Exhaust Fan None noted
Vents: Window Exhaust Fan None noted	
Caulking: Around tub/shower at walls and floor is	Caulking: Around tub/shower at walls and floor is
Loose Mildewed MissingRe-caulk as required	Loose Mildewed MissingRe-caulk as required
Leaks: None noted	Leaks: None noted
Noted at Tub Shower Sink Bidet	Noted at TubShowerSinkBidet
From fixture From faucets	From fixture From faucets
Electrical; Ground Fault Interrupter Install GFI	Electrical: Ground Fault Interrupter Install GFI
No recentacles	No receptacles
- No leceptacies	
No receptacles Plumbing noted on exterior wall, unacceptable	Plumbing noted on exterior wall, unacceptable
Plumbing noted on exterior wall, unacceptable	Pidifibilig floted off exterior wall, disacceptable
BATHROOM 3: Full Partial	BATHROOM 4: Full Partial
BATHROOM 3: Full Partial	BATHROOM 4: Full Partial
BATHROOM 3: Full Partial Location None noted	Location
Tub:Built inLeg TubNone noted	Tub:Built inLeg TubNone noted
Tub:Built inLeg TubNone noted Shower:with TubStall	Tub: Built in Leg Tub None noted Shower: with Tub Stall
Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic	Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure: Plastic Ceramic
Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo	Location Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wall Yes No
Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged groutEvidence of moisture behind tiles	Location Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged groutEvidence of moisture behind tiles
Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged groutEvidence of moisture behind tiles	Location Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNoMissing/damaged groutEvidence of moisture behind tiles Sink(s): #VanityWall HungPedestal
Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged groutEvidence of moisture behind tiles Sink(s): #VanityWall HungPedestal Feels adequately fastened Yes No	Location Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNoMissing/damaged groutEvidence of moisture behind tiles Sink(s): #VanityWall HungPedestal Feels adequately fastenedYesNo
Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged groutEvidence of moisture behind tiles Sink(s): #VanityWall HungPedestal Feels adequately fastened Yes No	Location Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNoMissing/damaged groutEvidence of moisture behind tiles Sink(s): #VanityWall HungPedestal Feels adequately fastenedYesNo
Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged groutEvidence of moisture behind tiles Sink(s): #VanityWall HungPedestal Feels adequately fastened Yes No	Location Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNoMissing/damaged groutEvidence of moisture behind tiles Sink(s): #VanityWall HungPedestal Feels adequately fastenedYesNo
Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged grout Evidence of moisture behind tiles Sink(s): # VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on	Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged groutEvidence of moisture behind tiles Sink(s): #VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on
Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged grout Evidence of moisture behind tiles Sink(s): # VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on Feels adequately fastenedYesNo	Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged groutEvidence of moisture behind tiles Sink(s): #VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on Feels adequately fastenedYesNo
Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged grout Evidence of moisture behind tiles Sink(s): # VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped	Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged groutEvidence of moisture behind tiles Sink(s): #VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped
Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged grout Evidence of moisture behind tiles Sink(s): # VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps	Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged grout Evidence of moisture behind tiles Sink(s): # VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None noted Turned on Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps
Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged grout Evidence of moisture behind tiles Sink(s): # VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped	Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged groutEvidence of moisture behind tiles Sink(s): #VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic Tile
Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged groutEvidence of moisture behind tiles Sink(s): #VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic Tile Soft or weak spots noted in floor	Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged grout Evidence of moisture behind tiles Sink(s): # VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic Tile Soft or weak spots noted in floor
Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged groutEvidence of moisture behind tiles Sink(s): #VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic Tile Soft or weak spots noted in floor	Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged grout Evidence of moisture behind tiles Sink(s): #VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic TileSoft or weak spots noted in floor Vents:WindowExhaust FanNone noted
Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged groutEvidence of moisture behind tiles Sink(s): #VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic Tile Soft or weak spots noted in floor Vents:WindowExhaust FanNone noted	Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged grout Evidence of moisture behind tiles Sink(s): #VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic TileSoft or weak spots noted in floor Vents:WindowExhaust FanNone noted
Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged grout Evidence of moisture behind tiles Sink(s): #VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic TileSoft or weak spots noted in floor Vents:WindowExhaust FanNone noted Caulking: Around tub/shower at walls and floor is	Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged groutEvidence of moisture behind tiles Sink(s): #VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic Tile Soft or weak spots noted in floor Vents:WindowExhaust FanNone noted Caulking: Around tub/shower at walls and floor is
Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged grout Evidence of moisture behind tiles Sink(s): # VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic Tile Soft or weak spots noted in floor Vents:WindowExhaust FanNone noted Caulking: Around tub/shower at walls and floor is LooseMildewedMissingRe-caulk as required	Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged groutEvidence of moisture behind tiles Sink(s): #VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic Tile Soft or weak spots noted in floor Vents:WindowExhaust FanNone noted Caulking: Around tub/shower at walls and floor is LooseMildewedMissingRe-caulk as required
Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged groutEvidence of moisture behind tiles Sink(s): # VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic Tile Soft or weak spots noted in floor Vents:WindowExhaust FanNone noted Caulking: Around tub/shower at walls and floor is LooseMildewedMissingRe-caulk as required Leaks:None noted	Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged groutEvidence of moisture behind tiles Sink(s): #VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic TileSoft or weak spots noted in floor Vents:WindowExhaust FanNone noted Caulking: Around tub/shower at walls and floor isLooseMildewedMissingRe-caulk as required Leaks:None noted
Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged grout Evidence of moisture behind tiles Sink(s): # VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic Tile Soft or weak spots noted in floor Vents:WindowExhaust FanNone noted Caulking: Around tub/shower at walls and floor is LooseMildewedMissingRe-caulk as required Leaks:None noted Noted atTubShowerSinkBidet	Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged grout Evidence of moisture behind tiles Sink(s): # VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None noted Turned on Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic TileSoft or weak spots noted in floor Vents:VindowExhaust FanNone noted Caulking: Around tub/shower at walls and floor isLooseMildewedMissingRe-caulk as required Leaks:None noted Noted atTubShowerSinkBidet
Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged grout Evidence of moisture behind tiles Sink(s): # VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic Tile Soft or weak spots noted in floor Vents:WindowExhaust FanNone noted Caulking: Around tub/shower at walls and floor is LooseMildewedMissingRe-caulk as required Leaks:None noted Noted atTubShowerSinkBidet From fixtureFrom faucets	Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged grout Evidence of moisture behind tiles Sink(s): # VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic TileSoft or weak spots noted in floor Vents:WindowExhaust FanNone noted Caulking: Around tub/shower at walls and floor isLooseMildewedMissingRe-caulk as required Leaks:None noted Noted atTubShowerSinkBidet From fixtureFrom faucets
Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged grout Evidence of moisture behind tiles Sink(s): # VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic Tile Soft or weak spots noted in floor Vents:WindowExhaust FanNone noted Caulking: Around tub/shower at walls and floor is LooseMildewedMissingRe-caulk as required Leaks:None noted Noted atTubShowerSinkBidet From fixtureFrom faucets	Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged grout Evidence of moisture behind tiles Sink(s): # VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None noted Turned on Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic Tile Soft or weak spots noted in floor Vents:WindowExhaust FanNone noted Caulking: Around tub/shower at walls and floor is LooseMildewedMissingRe-caulk as required Leaks:None noted Noted atTubShowerSinkBidet From fixtureFrom faucets Electrical:Ground Fault InterrupterInstall GFI
Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged groutEvidence of moisture behind tiles Sink(s): #VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic Tile Soft or weak spots noted in floor Vents:WindowExhaust FanNone noted Caulking: Around tub/shower at walls and floor is LooseMildewedMissingRe-caulk as required Leaks:None noted Noted atTubShowerSinkBidet From fixtureFrom faucets Electrical:Ground Fault InterrupterInstall GFI	Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged grout Evidence of moisture behind tiles Sink(s): # VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic TileSoft or weak spots noted in floor Vents:WindowExhaust FanNone noted Caulking: Around tub/shower at walls and floor isLooseMildewedMissingRe-caulk as required Leaks:None noted Noted atTubShowerSinkBidet From fixtureFrom faucets
Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged grout Evidence of moisture behind tiles Sink(s): # VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic Tile Soft or weak spots noted in floor Vents:WindowExhaust FanNone noted Caulking: Around tub/shower at walls and floor is LooseMildewedMissingRe-caulk as required Leaks:None noted Noted atTubShowerSinkBidet From fixtureFrom faucets	Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged grout Evidence of moisture behind tiles Sink(s): # VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None noted Turned on Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted at TubShowerSinkBidet Taps Floor:VinylCeramic Tile Soft or weak spots noted in floor Vents:WindowExhaust FanNone noted Caulking: Around tub/shower at walls and floor is Loose MildewedMissingRe-caulk as required Leaks:None noted Noted at TubShower SinkBidet From fixture From faucets Electrical: Ground Fault Interrupter Install GFI
Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged groutEvidence of moisture behind tiles Sink(s): #VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic Tile Soft or weak spots noted in floor Vents:WindowExhaust FanNone noted Caulking: Around tub/shower at walls and floor is LooseMildewedMissingRe-caulk as required Leaks:None noted Noted atTubShowerSinkBidet From fixtureFrom faucets Electrical:Ground Fault InterrupterInstall GFI No receptacles	Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged groutEvidence of moisture behind tiles Sink(s): # VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None noted Turned on Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic Tile Soft or weak spots noted in floor Vents:WindowExhaust FanNone noted Caulking: Around tub/shower at walls and floor is LooseMildewedMissingRe-caulk as required Leaks:None noted Noted atTubShowerSinkBidet From fixtureFrom faucets Electrical:Ground Fault InterrupterInstall GFI No receptacles
Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged groutEvidence of moisture behind tiles Sink(s): #VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None notedTurned on Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic Tile Soft or weak spots noted in floor Vents:WindowExhaust FanNone noted Caulking: Around tub/shower at walls and floor is LooseMildewedMissingRe-caulk as required Leaks:None noted Noted atTubShowerSinkBidet From fixtureFrom faucets Electrical:Ground Fault InterrupterInstall GFI	Tub:Built inLeg TubNone noted Shower:with TubStall Enclosure:PlasticCeramic Seems adequately fastened to wallYesNo Missing/damaged grout Evidence of moisture behind tiles Sink(s): # VanityWall HungPedestal Feels adequately fastenedYesNo Toilet:Flushed, Feels adequately securedYesNo Bidet:None noted Turned on Feels adequately fastenedYesNo Damage:None NotedCracked / Chipped Noted atTubShowerSinkBidetTaps Floor:VinylCeramic Tile Soft or weak spots noted in floor Vents:WindowExhaust FanNone noted Caulking: Around tub/shower at walls and floor is LooseMildewedMissingRe-caulk as required Leaks:None noted Noted atTubShowerSinkBidet From fixtureFrom faucets Electrical:Ground Fault InterrupterInstall GFI

Have all above items corrected by a plumber or other appropriate contractor before items deteriorate further.

Fireplaces & Common Safety Devices

None noted LocationMasonryMetal prefabricatedWood Stove InsertGas InsertWorking Firebox:MetalMasonry Firebrickloose mortarAbnormal openings (Cracks, missing grout, etc.) Flue:Dirtysharedmissing linerClearance Damper:Opened and closedCould not open & close safelyBroken or missing partsdiddid not observe flue liner Combustion air supply:InteriorExterior air Limitations:Fire burning area blocked, unable to inspect	Ground Fault Interrupter (GFI) Protection No GFIs noted in house wiringGFI(s) noted in panel boxGFIs noted in branch outletsGFI(s) noted on exterior Testing & Results:using an electric tester plugged into outletusing test button on GFI. All devices testedDIDDID NOT trip, as expected. Course of Action:GFIs should be retested & repaired/replaced by electrician and more added, as neededGFIs should be installed	
Pilot light was off during inspection Course of Action: Have WETT Certified contractor clean, test, evaluate and certify before use Have fireplaces cleaned annually by a chimney sweep Fireplace # 2	Smoke Detectors None Noted, have an electrician install immediately #Smoke Detectors X Not Tested as may be connected to wired / wireless alarm system in house, they should be tested by alarm company before sleeping in house.	
Location MasonryMetal prefabricatedWood Stove InsertGas InsertWorking Firebox:	Course of Action: Install additional smoke detectors upper floormain floorBasement Within 5 feet of bedroom doors Replace smoke detectors Relocate smoke detectors X Test smoke detectors monthly X Test smoke detectors before sleeping in the house	
Limitations: Fire burning area blocked, unable to inspectPilot light was off during inspection Course of Action: Have WETT Certified contractor clean, test, evaluate and certify before use Have fireplaces cleaned annually by a chimney sweep	Carbon Monoxide (CO) Detectors No permanently installed CO detectors noted CO Detectors X Not Tested as may be connected to wired / wireless alarm system in house, they should be tested by alarm company before sleeping in house.	
Wood Stove None noted Location	Install CO detector in hall on all sleeping levels at knee level X Test CO detectors before sleeping in the house	
Fire burning at time of inspection, unable to inspect Have WETT Certified contractor clean, test and evaluate Have clearances of wood stove and flue pipes evaluated by a WETT Certified Contractor Have WETT Certified contractor evaluate condition and clearances of wood stove and flue pipes	Interior Fire Sprinkler System None Noted Noted, have evaluated for proper operation Sprinklers are not tested, because to do so would cause flooding and damage to furnishings in the home. Have system evaluated by an appropriate contractor.	

Course of Action: Have an electrician install safety devices before sleeping in the home

General Interior

Ceilings DrywallWoodMetalAcoustic ceiling tiles Plaster overWood lathMetal meshwall board Unknown backer material Appears recently painted / paperedNail pops were noted No major defects were noted Water stains inarea Appears dry, monitor over time The following major defects were noted:	Mainly door types of:Hollow coreWoodPlasticHinged one sideBi-foldLouveredMirroredSliders Defects noted:Some adjustments could be made to the door fitDoors do not open and close easilyDoors or hinges feel/look looseDoors with holes & broken partsDoors missing from opening which normally would be
Walls Drywall Wood Panel covered Plaster over: Wood lath Metal mesh wall board Unknown backer material Unknown materials No major defects were noted Appears recently painted / papered Nail pops were noted The following major defects were noted:	expected to have doors.
Wall to wall carpetRoom sized rugsHardwoodLaminated WoodPlywoodSheet goodsVinyl tilesCeramic tile When bounced on,a normal amount of bounce was notedexcessive bounce was notedexcessive bounce was notedupper floor, monitor for ongoing movement Trim	They appear to be made of:WoodMetalPlasticA combination of materialsUnknown Random tested windows and found Window SashDoDo not open under normal pressure **Basement window(s):None notedWoodMetalPlastic Sash are locatedhigh near ceiling and openinoutslide sideways
None noted (base of walls, around doors & windows) Mainly, material type of:WoodPlastic Trim isPaintedStainedUnfinished Paint or finish was observed to be peeling. Trim was observed to beloosemissing in a fewmost places Stairs, Balconies, & Railings	Defects: See led Shu + Cold Cold Cold Cold Cold Cold Cold Cold
To BasementTo AtticBetween living levelsFelt solid under foot, rise and run felt about even Trip hazards observed:	Fogged up / Condensation notedbroken thermal sealsRecommend replace windows for energy conservation
Uneven rise and run from step to step Weak or springy treads or stringers Loose treads Low head room Shallow treads noted Loose handrails noted on stairs	Skylights and Roof Windows None noted from interior Appear fixedOperateddid not operate Results:
Loose carpet or tread coverings Large openings in rail system should be closed down Steep steps (rise too high) No handrails noted on Basement stairs Course of Action:Add handrail for safety	SomeMost seem to have insulated glazing (glass) Leaks (around unit):None noted Small stains noted Excessive staining/damage noted Condensation/Leaks (abutting glass)None noted Small stains notedExcessive stains noted Active water penetration observed
Additional Comments or Issues:	

Course of Action: Have a carpenter or home improvement contractor correct defects noted above

Attic & Ventilation

Attic Access	Attic Ventilation
No Attic Flat roof Cathedral ceiling No Access Blocked by storage items	No ventilation noted, it may or may not exist
Blocked by storage items	Type:
Stairs, see Stairs on INTERIOR page	Ridge vent
Pull down in	Roof vent
Access Hatch in	Gable end vent
	Soffit / Fascia vent Turbines
Results: Limited viewing, looked in through opening ONLY	Whole house fan
Due to: low headroomno walkway/floorStorage	Other
Entered, walked from end to end	
Entry blocked by excessive storage which also	Vents obstructed by:Insulationnest / hives
prevented sufficient viewing of attic area.	
Land the Market and the batch	Exhaust venting fans noted in ceilings below attic floor with
InsulateWeatherstrip access hatch	nothing noted in attic to indicate they vent directly to exterior.
	Hothing folds in add to indicate they rent already to extend.
Framing	Defects:
RaftersTrusses /U/4	Inadequate ventilation, increase venting
Sheathing	Exhaust fans from interior end in attic and must be
Structural panelsSpaced boards	directed to exterior.
	Remove insulation that is currently blocking vents, install soff
Defects:	baffles Soffit vents missing baffles, should be installed
SaggingBuckling CrackingRot	Solit verits missing barries, should be installed
Delaminating	
	AND
Course of Action:	Course of Action:
Localized defects, monitor over time	
Add or secure structural supports	-
Seal party / fire walls	Crawl Space Ventilation
	Not Applicable
Moisture & Water Penetration	Not Applicable
None noted N/A	Wall vents observed
Evidence observed in attic:	Vents into basement area
Dark stains on framing	
Microbial growth / mildew	
Rust / corrosion on roofing nails	Recommend adding ventilation to this area to prevent
Delaminated or decomposing roof decking material	condensation / moisture problems
Water damage	Additional information on the crawl space ventilation is noted
Water stains Condensation evident on exhaust pipes	in the Crawl Space section of the report.
	White Particular Continue (Control Control
Course of Action:	Attic Storage
Insulate exhaust vents in attic	Not recommended
Increase Insulation on pipes	Limited storage
Have a contractor inspect and repair/rebuild as needed	Attic fully floored
Further evaluation and testing for possible mould recommended	
(and remediation work performed as required)	
Additional Comments or Issues:	

Course of Action: Have a roofing or other appropriate contractor evaluate and repair as needed.

Insulation

11/1	
Attic MA	Ductwork
None noted Attic could not be accessed	None noted
Fully flooredSome observed, mostly obscured	Somemost ductwork in unconditioned spaces
Form:	was observed to be insulated.
Batt / BlanketLoose FillRigid Board	
Foamed in Place	Insulation appears to beadequateinsufficient
	Observed:CondensationRust
Type:	Uninsulated ducts should be insulated for energy conservation and to
Glass FiberWood ShavingsMineral Fiber	prevent condensation and resultant damage.
Cellulose FiberUrea Formaldehyde Foam (UFFI)	
Plastic/Foam BoardVermiculite, test for Asbestos content	Pipes
Other	None noted Heating cables
Location:	Somemany pipes believed to be carrying heated
RoofBothother	or chilled water or coolants in unconditioned spaces were
	observed to be insulated.
Estimated thicknessInchesUnknown	Insulation appears to be adequateinsufficient
OTINIOWIT	Uninsulated pipes should be insulated for energy conservation and to
Estimated R-value R	
	prevent condensation and resultant damage.
Defects:	
WetCompressedMildew / fungus	Walls
Evidence of past or current rodent infestation	Not determined
Insulation appears, smells or feels damp/wet, replacing	Through hole in wall(located
should improve efficiency & reduce allergies.	sawtype of insulation
Low / bare spots in insulation, recommend additional insulation	70.000
Vanour harrier: None Noted Not visible	Removed #exterior wall outlet covers on interior
Vapour barrier:None NotedNot visiblePlasticKraft PaperPolyethylene	of house and saw
Other Not determined	While the above does not determine that the walls are or are not insulated
Barrier is located on warm side of the insulation	it may give an indication of what is in the walls. Sometimes insulation
Barrier is victaied on warm side of the insulation Barrier is within insulation or on cold side, have repaired	is placed behind electrical boxes and nowhere else.
	is placed berlind electrical boxes and nowhere else.
Exhaust pipes from interior:	
Adequate insulationwetcondensation	Building Underside
Clearances	Not Applicable
Adequate around pot lights, fans other mechanical items	None noted
Electrical wiring observed within or on top of insulation, have	From within a crawl space / basement, under floor of the
secured.	lowest living areainsulation was observed.
Course of Action:	
Adding additional insulation should be considered to	Estimated thickness inches thick
ncrease energy efficiency of home.	Estimated R-value ofR.
Additional Comments or Issues:	
Course of Action: Have an appropriate contra	actor replace or add insulation where needed.
	2-12-12-13
	imitations
Normal furnishings and floor, ceiling, and wall coverings will obstruct the	ne view of the inspector. In addition to the standard obstructions, the
A STATE OF THE PARTY OF THE PAR	
ollowing Items further limited the inspection:	
	Interior
Exterior	Interior
Exterior plantings too close to building	Furnishings throughout the house
Exterior plantings too close to building snow and ice buildup vines on the building	Furnishings throughout the house
plantings too close to building snow and ice buildup vines on the building debris, leaves, brush, wood or other items piled against	Furnishings throughout the housenormalminimal,excessive Stored items:
plantings too close to building snow and ice buildup vines on the building debris, leaves, brush, wood or other items piled against exterior of building	Furnishings throughout the house normal minimal, excessive Stored items: throughout the house, basement, attic
plantings too close to building snow and ice buildup vines on the building debris, leaves, brush, wood or other items piled against exterior of building Other	Furnishings throughout the housenormalminimal,excessive Stored items:
plantings too close to building snow and ice buildup vines on the building debris, leaves, brush, wood or other items piled against exterior of building	Furnishings throughout the house excessive Stored items: basement, attic
plantings too close to building snow and ice buildup vines on the building debris, leaves, brush, wood or other items piled against exterior of building Other	Furnishings throughout the housenormalminimal,excessive Stored items:throughout the house,basement,atticnormalminimal,excessive

Page 38 of 38